

ASS. REC. BY:

REF:

AIS/ 23006217/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5585K

Yr Regn:

08.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c

1798

Colour

m.p White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

55883

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31-UXO-3095986

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

Continental 195/65R15

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

4 mm

L/Bal.

9

mm

L/Bal.

9

4 mm

D.O.A.

14/6/23

D.O.I.

20/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/6 @ 3390.72 Cash

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Available
Running B4peing

83390.72

Sunday @ 17/06

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHC5585K

AAD2306-059

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

20 JUN 2023

SHC5585K

JTDKB3FUX03095986

200303878K

TOYOTA

PRIUS GEN 4

14/6/2023

SLM5573U/ Allianz

31/8/2022

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	612.68	✓
\$	27.93	X
\$	472.19	✓
\$	149.21	X
\$	149.21	X
\$	167.48	✓
\$	167.48	X
\$	419.90	✓
\$	49.25	X
\$	49.25	X
\$	220.50	X
\$	304.92	X
\$	290.43	✓
\$	159.39	X
\$	824.46	X
\$	1,156.89	✓
\$	68.88	✓
\$	68.88	✓
\$	90.30	✓

TOTAL \$ 5,449.23
25% \$ 1,362.31
\$ 4,086.92

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT

\$	700.00	X
\$	65.00	60.00
\$	60.00	X
\$	180.00	30.00
\$	150.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2306-**SHC5585K**

1	WINDSCREEN MOULDING	\$	na	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
TOTAL		\$		1,485.00	
TOTAL PARTS		\$		5,571.92	

LABOUR

To rust-proofing of the affected areas.	\$	na	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	3001
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
To check steering geometry and computer wheel alignment	\$	na	220.00	X
TOTAL	\$		4,910.00	
OVERALL TOTAL	\$		10,481.92	

2nd day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: