

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

DATE: 15.06.2023

YN 78G

MODEL: Toyota Prius

INSURANCE: CHINA TAIPING (45)

VEHICLE NO.: SHA3343R

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$503.04	de
	Rear Bumper Under Cover	1		\$654.96	X
	Rear Bumper Side Retainer LH	1		\$112.70	de
	Rear Bumper Clips	10	\$2.20	\$22.00	net
	Rear Bumper Lower Extension LH	1		\$232.00	Ry
	Rear Fender LH	1		\$992.04	Ry
	Rear Fender Shield LH	1		\$134.20	X
	TailLamp Upper LH	1		\$557.90	cha
	TailLamp Lower LH	1		\$570.00	cha
	SUB TOTAL			\$3,778.84	
	LESS 25%			\$944.71	
	DISCOUNTED PARTS TOTAL			\$2,834.13	
	Rear Bumper Mat	1		\$50.00	NETT
	Rear Fender (Petrol Only) LH	1		\$40.00	NETT
	Labour Charge				
	Panel Beating		700	\$1,200.00	
	Spray Painting Charge		500	\$600.00	
	Check Lightings		30	\$40.00	
	Remove/Refix Reverse Sensor		30	\$120.00	
	TOTAL LABOUR			\$1,960.00	
	ESTIMATE TOTAL			\$4,884.13	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 in 15/6/23 2430pm
 3 days
 Tanpin @ Pelandan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date/Time: 15.06.2023 08:39

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5900270

JC NO305557629

OMER	REGN NO: SHA3343R	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OMER NO 7010045	MODEL	E.....1/2.....F
ESS 383 SIN MING DRIVE	PRIUS HYBRID(G4)14.06.2023 14:25	DATE/TIME IN
Singapore SINGAPORE 575717	YR OF MANU	TARGET DATE
(R) 65508755 (O)	10.08.2017	
(P)	CHASSIS CODE	COMPLETION DATE/TIME:
JUNT CARD NO.	JTDKB3FUX03563165	


JOB DESCRIPTION

Accident Date: 14.06.2023

ATURE: 3P 14.06.2023

NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHA3343R-TP



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHA3343R

LIMITS

Vehicle No.:

SHA3343R

vice Advisor

Signature/Date

Name of Service Advisor