



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

Ref: CS/HSB23006237/y3

Date: 20/06/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2186D	Veh. Inspected	PC 5353T
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04NFS	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	20/06/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/06/2023	Inspection Date	28/06/2023
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--