



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SG Truck Automotive Pte Ltd
18 Benoi Road
Singapore 629890
Email: admin@sgtruckat.com
Tel: 9021 1212

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

DATE

:20/6/2022

Attention: Motor Claim Department

SHEET NO. 1 OF 1 SHEET

RE : VEHICLE NO : GBF3904S NISSAN

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	TAILGATE <i>bt</i>		3,550.00 <i>2101</i>
2	1	REAR BUMPER <i>de</i>	2888.70	1,085.00 <i>632.70</i>
3	1	REAR BUMPER UPPER COVER <i>Xnn</i>	15%	388.00 <i>X</i>
4	1	TAILGATE MOULDING <i>nn</i>	2455.39	487.00 <i>155</i>
5	1	TAILGATE INNER TRIM <i>Xnn</i>		553.00 <i>X</i>
6	1	TAILGATE LOCK <i>Xnn</i>		432.00 <i>X</i>
LESS 15%			\$	6,495.00
			\$	5,845.50

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
SPECIAL NET				
1	1	8 PAX <i>nn</i>	\$	35.00 <i>10</i>
2	1	70KM /H <i>nn</i>	\$	35.00 <i>10</i>
3	1	TAILGATE NISSAN EMBELM <i>nn</i>	\$	210.00 <i>78</i>
4	1	TAILGATE NV350 EMBLEM <i>nn</i>	\$	222.00 <i>56</i>
5	1	TAILGATE URVAN EMBLEM <i>nn</i>	\$	188.00 <i>55</i>
6	1	REAR NUMBER PLATE <i>Xnn</i>	\$	35.00 <i>Xnn</i>
7	1	REVERSE SENSOR <i>nn</i>	\$	287.00 <i>200</i>

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary straighten front floor panel repair, reshape body dented panel in accordance to factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,200.00 <i>550</i>
2	1	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,000.00 <i>550</i>
3	1	To check and reconnet wiring reverse sensor	300.00 <i>50</i>
4	1	To remove and refit tailgate windscreen	150.00 <i>120</i>
<i>4134.39</i> <i>20%</i> <i>3307.51</i> <i>4/5 - \$3,300 / 4 days</i>			<i>Resur</i> <i>4/5 20010068</i> <i>4 days</i> <i>4/5</i> <i>20/06/23</i> <i>Resur after repair</i>