

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2306-401
DATE : 19-Jun-2023
POLICY NO. : P10897555R00
VEHICLE REG. NO. : SLN948A
VEHICLE MAKE : HONDA GRACE 1.5LX CVT

TO Motor Claim Department
AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
190 Clemenceau Avenue #03-01,
Singapore Shopping Centre, Singapore 239924
Tel: 6221 2199 Fax: 67250853

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper <i>de</i>	1	\$ 215.00	\$ 215.00
2	Front Bumper Clips <i>m</i>	10	\$ 2.50	\$ 25.00
3	Front Bumper Undercover <i>cut</i>	1	\$ 60.00	\$ 60.00
4	Front Bumper Under Rubber Skirt <i>at</i>	1	\$ 75.00	\$ 75.00
5	Front Tow Eye Cover <i>X</i>	1	\$ 12.00	\$ 12.00
6	Front Reinforcement <i>SA</i>	1	\$ 215.00	\$ 215.00
7	Front Bumper Retainer RH <i>m</i>	1	\$ 15.00	\$ 15.00
8	Front Bumper Retainer LH <i>m</i>	1	\$ 15.00	\$ 15.00
9	Front Radiator Grille <i>cm</i>	1	\$ 90.00	\$ 90.00
10	Front Radiator Grille Moulding <i>cm</i>	1	\$ 110.00	\$ 110.00
11	Front Radiator Grille Lower <i>cm de</i>	1	\$ 30.00	\$ 30.00
12	Front Emblem <i>m</i>	1	\$ 20.00	\$ 20.00
13	Head Lamp RH <i>cm</i>	1	\$ 1,200.00	\$ 1,200.00
14	Head Lamp LH <i>?</i>	1	\$ 1,200.00	\$ 1,200.00
15	Head Lamp Bracket LH <i>cm</i>	1	\$ 30.00	\$ 30.00
16	Head Lamp Bracket RH <i>cm</i>	1	\$ 30.00	\$ 30.00
17	Fog Lamp Garnish Cover LH <i>cut</i>	1	\$ 20.00	\$ 20.00
18	Fog Lamp Garnish Cover RH <i>cut</i>	1	\$ 20.00	\$ 20.00
19	Front Engine Cover RH <i>bt</i>	1	\$ 25.00	\$ 25.00
20	Front Engine Cover LH <i>bt</i>	1	\$ 25.00	\$ 25.00
21	Front Undercarriage Cover <i>com</i>	1	\$ 65.00	\$ 65.00
22	Front Undercarriage Clip <i>m</i>	10	\$ 2.50	\$ 25.00
23	Front Bonnet <i>bt</i>	1	\$ 360.00	\$ 360.00
24	Front Bonnet Lock <i>?</i>	1	\$ 80.00	\$ 80.00
25	Front Bonnet Hinge LH <i>X</i>	1	\$ 48.00	\$ 48.00
26	Front Bonnet Hinge RH <i>X</i>	1	\$ 48.00	\$ 48.00
27	Front Bonnet Insulator Clip <i>m</i>	10	\$ 2.50	\$ 25.00
28	Front Bonnet Rubber Seal <i>m</i>	1	\$ 24.00	\$ 24.00
29	Front Bonnet Stopper (Small) LH <i>m</i>	1	\$ 12.00	\$ 12.00
30	Front Bonnet Stopper (Small) RH <i>m</i>	1	\$ 12.00	\$ 12.00
31	Front Fender RH <i>repair</i>	1	\$ 235.00	\$ 235.00
32	Front Fender Shield RH <i>cm</i>	1	\$ 48.00	\$ 48.00



38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2306-401
DATE : 19-Jun-2023
POLICY NO. : P10897555R00
VEHICLE REG. NO. : SLN948A
VEHICLE MAKE : HONDA GRACE 1.5LX CVT

TO Motor Claim Department
AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
190 Clemenceau Avenue #03-01,
Singapore Shopping Centre, Singapore 239924
Tel: 6221 2199 Fax: 67250853

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	Front Fender Shield LH <i>corn</i>	1	\$ 48.00	\$ 48.00
34	Front Fender Clips <i>corn</i>	10	\$ 2.50	\$ 25.00
35	Front Support Panel ?	1	\$ 260.00	\$ 260.00
36	Radiator ?	1	\$ 660.00	\$ 660.00
37	Radiator Shroud ?	1	\$ 60.00	\$ 60.00
38	Radiator Fan Blade ?	1	\$ 36.00	\$ 36.00
39	Radiator Fan Motor <i>X</i>	1	\$ 160.00	\$ 160.00
40	A/C Condenser <i>bt</i>	1	\$ 360.00	\$ 360.00
41	A/C Shroud ?	1	\$ 65.00	\$ 65.00
42	A/C Fan Blade ?	1	\$ 60.00	\$ 60.00
43	A/C Fan Motor <i>X</i>	1	\$ 160.00	\$ 160.00
44	A/C Compressor <i>X</i>	1	\$ 1,300.00	\$ 1,300.00
45	A/C Compressor Discharge Hose ?	1	\$ 75.00	\$ 75.00
46	A/C Compressor Receiver Pipe ?	1	\$ 110.00	\$ 110.00
47	A/C Compressor Suction Hose ?	1	\$ 85.00	\$ 85.00
48	Radiator Spare Tank <i>X</i>	1	\$ 36.00	\$ 36.00
49	Wiper Spare Tank <i>X</i>	1	\$ 30.00	\$ 30.00
50	Wiper Spare Tank Motor <i>X</i>	1	\$ 36.00	\$ 36.00
51	Engine Timing Cover RH ?	1	\$ 115.00	\$ 115.00
52	Engine Timing Cover Bracket RH ?	1	\$ 100.00	\$ 100.00
53	Engine Mounting Rear ?	1	\$ 75.00	\$ 75.00
54	Engine Mounting RH <i>corn</i>	1	\$ 120.00	\$ 120.00
55	Engine Mounting LH ?	1	\$ 120.00	\$ 120.00
56	Engine Oil Sump Pan ?	1	\$ 195.00	\$ 195.00
57	Charging Alternator ?	1	\$ 420.00	\$ 420.00
58	Front Fan Belt ?	1	\$ 60.00	\$ 60.00
59	Front Absorber RH ?	1	\$ 115.00	\$ 115.00
60	Front Absorber Top Mount RH ?	1	\$ 35.00	\$ 35.00
61	Front Lower Arm RH ?	1	\$ 135.00	\$ 135.00
62	Front Tie Rod RH ?	1	\$ 55.00	\$ 55.00
63	Front Tie Rod End RH ?	1	\$ 55.00	\$ 55.00
64	Front Stabiliser Bar ?	1	\$ 250.00	\$ 250.00
65	Front Stabiliser Linkage RH ?	1	\$ 48.00	\$ 48.00

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2306-401

DATE : 19-Jun-2023

POLICY NO. : P10897555R00

VEHICLE REG. NO. : SLN948A

VEHICLE MAKE : HONDA GRACE 1.5LX CVT

TO Motor Claim Department
AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
 190 Clemenceau Avenue #03-01,
 Singapore Shopping Centre, Singapore 239924
 Tel: 6221 2199 Fax: 67250853

FOR SURVEYOR

*Resurvey - Hq 900 100 68
 8 days / L/S / 20/06/23 @ 1700
 REVENUE / EXCESS. TBA
 Resurvey after repair*

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
66	Front Driveshaft RH ?	1	\$ 1,250.00	\$ 1,250.00
67	Front Wheel Bearing RH ?	1	\$ 110.00	\$ 110.00
68	Front Wheel Hub RH ?	1	\$ 100.00	\$ 100.00
69	Front Wheel Knurkle RH ?	1	\$ 100.00	\$ 100.00
70	Front CrossMember ?	1	\$ 400.00	\$ 400.00
	Part Cost Plus 10%			\$ 1,183.80
Total Spare Parts				\$ 13,021.80
SPECIAL NETT				
71	Front License Plate <i>can</i>	1	\$ 35.00	\$ 35.00
72	Michelin tyres 185/60 R15 <i>from car / 70%</i>	2	\$ 180.00	\$ 360.00
73	Front 15R Rim RH <i>can</i>	1	\$ 300.00	\$ 300.00
74	Rear 15R Rim RH <i>can</i>	1	\$ 300.00	\$ 300.00
75	Engine Oil 4L <i>oil</i>	1	\$ 60.00	\$ 60.00
76	Auto Transmission Oil 4L <i>oil ?</i>	1	\$ 60.00	\$ 60.00
77	4L Coolant <i>oil ?</i>	1	\$ 35.00	\$ 35.00
Total Special Nett				\$ 1,150.00
LABOUR				
78	Spray Painting Whole Front, Sill Panel RH Including Blending	1	\$ 1,000.00	\$ 1,000.00 <i>\$800</i>
79	Remove, Refit and Repair Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00 <i>\$800</i>
80	Computerised Wheel Alignment	1	\$ 70.00	\$ 70.00 ✓
81	Remove and Refit Engine to facilitate Repair Work	1	\$ 280.00	\$ 280.00 <i>\$150</i>
82	Remove, Refit & Replace Front Undercarriage RH	1	\$ 180.00	\$ 180.00 <i>\$120?</i>
83	Remove and Refit A/C Condenser, Radiator Including A/C Gas	1	\$ 100.00	\$ 100.00 <i>\$80</i>
84	Check and Rectify Electrical Wiring	1	\$ 20.00	\$ 20.00 ✓
Total Labour				\$ 2,650.00
Amount Before Excess				\$ 16,821.80
Add GST @ 8%				1,345.74
Total Amount Payable				\$ 18,167.54

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: