

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SJP8495A

Make & Model: Toyota Picnic

Chassis number: JTEGH23B700026476

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <i>bt</i> 1,109.50
2	Tailgate centre emblem	1	\$ <i>ner</i> 78.30
3	Tailgate "TOYOTA" emblem	1	\$ <i>ner</i> 68.10
4	Tailgate "PICNIC" emblem	1	\$ <i>ner</i> 78.30
5	Tailgate windscreen glass rubber moulding	2	\$ <i>ner</i> 286.30
6	Tailgate lock	1	\$ <i>bt</i> 405.20
7	Tailgate lock catch	1	\$ <i>X</i> 56.00
8	Tailgate RH lamp	1	\$ <i>OK</i> 377.50
9	Tailgate LH lamp	1	\$ <i>int</i> 377.50
10	Tailgate outer moulding	1	\$ <i>ang</i> 318.50
11	Tailgate outer moulding clips	1set	\$ <i>Zgner</i> 70.00
12	Tailgate RH number plate lamp	1	\$ <i>X</i> 77.00
13	Tailgate LH number plate lamp	1	\$ <i>X</i> 77.00
14	Tailgate opener switch	1	\$ <i>X</i> 109.20
15	Tailgate inner trim board	1	\$ <i>Cus</i> 343.20
16	Tailgate inner trim board clips	1set	\$ <i>Zone</i> 70.00
17	Tailgate weatherstrip	1	\$ <i>twi</i> 287.80
18	Rear bumper	1	\$ <i>de</i> 643.80
19	Rear bumper clips	1set	\$ <i>he</i> 80.00
20	Rear bumper RH side retainer	1	\$ <i>X</i> 80.20
21	Rear bumper LH side retainer	1	\$ <i>X</i> 80.20
22	Rear bumper RH damper bracket	1	\$ <i>X</i> 79.10
23	Rear bumper LH damper bracket	1	\$ <i>X</i> 79.10
24	Rear bumper RH reflector	1	\$ <i>X</i> 74.30
25	Rear bumper LH reflector	1	\$ <i>X</i> 74.30
26	Rear bumper RH towing cover	1	\$ <i>de</i> 55.00
27	Rear bumper LH towing cover	1	\$ <i>X</i> 55.00
28	RH tailamp assy	1	\$ <i>X</i> 463.10
29	RH tailamp gasket	1	\$ <i>X</i> 22.00
30	RH taillamp panel	1	\$ <i>X</i> 145.60
31	RH tailamp lock clips	1set	\$ <i>X</i> 22.00
32	LH tailamp assy	1	\$ <i>at</i> 463.10
33	LH tailamp gasket	1	\$ <i>X</i> 22.00
34	LH taillamp panel	1	\$ <i>X</i> 145.60
35	LH tailamp lock clips	1set	\$ <i>X</i> 22.00
36	End panel	1	\$ <i>bt</i> 656.80
37	End panel inner garnish	1	\$ <i>de</i> 199.30
38	End panel inner garnish clips	1set	\$ <i>Zoner</i> 45.00
39	Rear compartment panel	1	\$ <i>Bul</i> 1,009.00
40	Rear compartment panel mat cover	1	\$ <i>th</i> 772.10
41	Rear compartment panel mat cover clips	1set	\$ <i>Zoner</i> 80.00

42	Rear compartment panel top cover	1	\$ de 783.20
43	Rear LH fender inner trim	1	\$ de 506.60
44	Rear LH fender inner trim clips	1set	\$ X 60.00
45	Rear LH fender splash shield	1	\$ X 93.00
46	Rear LH fender splash shield clips	1set	\$ X 50.00
47	Rear RH fender inner trim	1	\$ de 506.60
48	Rear RH fender inner trim clips	1set	\$ X 60.00
49	Rear RH fender splash shield	1	\$ X 93.00
50	Rear RH fender splash shield clips	1set	\$ X 50.00
			\$ 11,760.40
		Parts less 25%	\$ 2,940.10
		Total:	\$ 8,820.30

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate windscreen glass sealant	1	\$ 60 80.00
2	Tailgate windscreen glass inner seal	1	\$ 40 60.00
3	Tailgate reverse camera	1	\$ X 700.00
4	Rear number plate	1	\$ X 70.00
5	Rear bumper reverse sensors	1set	\$ 200 320.00
6	Rear compartment panel joint sealant	1	\$ 40 90.00
7	End panel joint sealant	1	\$ 40 70.00
		Total:	\$ 1,390.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 700 1,800.00
2	Spray painting on affected areas and panels	\$ 800 1,600.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 60.00
5	Remove and refit tailgate windscreen glass to assist repair	\$ 120 220.00
6	Transfer and replace tailgate inner components to new tailgate	\$ 60 150.00
7	Remove and replace tailgate reverse camera to assist repair	\$ 30 100.00
8	Remove and replace rear bumper reverse sensors	\$ 30 100.00
9	Remove and replace rear inner boards and garnish to assist repair	\$ 60 400.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Total: \$ 2,710.00

Spare Parts: \$ 8,820.30

Special Nett: \$ 1,390.00

Labour: \$ 2,710.00

Total Amount: \$ 12,920.30

Tanji 17495715

at 21/6/23 @ 3:20pm

1/5 Resurvey after repair

Tanji @ Kuantan

06 days

- To check consistency of accident
- To check part prices.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	070J

Vehicle Details

Vehicle No.:	SJP8495A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	1AZH327619
Chassis No.:	JTEGH23B700026476
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,511.00
Original Registration Date:	14 Apr 2009
First Registration Date:	14 Apr 2009
Transfer Count:	2
Actual ARF Paid:	\$23,511.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,018.00
COE Rebate Amount:	\$19,082.00
Total Rebate Amount:	\$19,082.00

The information contained herein is correct as at 20 Jun 2023

OK



**SINGAPORE
POLICE FORCE**



T/20230620/2035

1 of 4

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20230620/2035

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/06/2023 12:12	Vide Report No.:	Station Diary No.: 50
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMAD IBRAHIM BIN OTHMAN	Address: APT BLK 710 JURONG WEST STREET 71 #03-22 SINGAPORE 640710
ID Type / ID No.: NRIC NO / S1712070J	Contact No.: Home/Office: Mobile: 94310879
Nationality: SINGAPORE CITIZEN	Email: ibrahim@sph.com.sg
Sex: Male Age: 58 Date of Birth: 03/04/1965	Type of Informant: Driver
Race: Indian	Language: English
Occupation: ADMIN EXECUTIVE	Driving Licence Information: Class: 3 Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Driver: No	Date/Time of Accident: 20/06/2023 08:35	Type of Location: Straight Road
Location: JURONG PORT ROAD				
Weather: Clear		Road Surface: Dry		
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GZ6357L	Lorry	NISSAN		Silver	Slightly Damaged	1
SJP8495A	Car	TOYOTA	PICNIC AUTO W/O ROOF RACK	Red	Slightly Damaged	0
YM88H	Lorry	MITSUBISHI	CANTER	White	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20230620/2035

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

2 of 4

Report No. T/20230620/2035

CONTINUATION OF REPORT

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJP8495A	NTUC Income Insurance Co-Operative Limited	5134796629	16/03/2023	13/04/2024

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver

Name	ISKANDAR BIN HASSAN	ID No.	S7730894F
Related Vehicle	GZ6357L (Lorry)	Contact No.	93225390
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver

Name	MOHAMAD IBRAHIM BIN OTHMAN	ID No.	S1712070J
Related Vehicle	SJP8495A (Car)	Contact No.	94310879
Hospital/Clinic	Horizon Medical Pte Ltd (Lim Clinic and Surgery)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Driver

Name	HEW KOK SENG	ID No.	G2871160W
Related Vehicle	YM88H (Lorry)	Contact No.	81190462
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20230620/2035

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 4

Report No. T/20230620/2035

CONTINUATION OF REPORT

Brief Details.

On 20/06/2023 at about 0835hrs, I was alone driving my car (red Toyota Picnic, vehicle registration no. SJP8495A) along Jurong Port Road towards AYE direction. It is a 2 way road and both 2 lanes. I was on the right lane and stopped wanting to turn into No.29 Jurong Port Road.

I noticed one pickup lorry (silver Nissan, vehicle registration no. GZ6357L) driving behind me. Suddenly while I was stationary, I felt a collision from my rear and my vehicle was pushed forward. I alighted from my vehicle and found out that behind the said pickup lorry, there was another lorry (white Mitsubishi Canter, vehicle registration no. YM88H, JM Ice company) that had collided into the pickup lorry and resulted in the pickup lorry colliding into my vehicle.

I took photographs of the accident and exchanged particulars with the 2 drivers. No traffic police or ambulance came to the scene. After that, I drove off and left the scene.

Due to the accident, my rear bumper, boot door, and the compartment inside were dented. The rear light covers were dislodged and reverse sensor was damaged. There are front and rear cameras installed in my car but I am unsure if the accident footage was captured.

Due to the accident, I felt that my neck, shoulders, and back were sprained. I went to Horizon Medical Pte Ltd (Lim Clinic and Surgery) and was given Medical Certificate for 5 days from 20/06/2023 to 24/06/2023.



**SINGAPORE
POLICE FORCE**



T/20230620/2035

4 of 4

Report No. T/20230620/2035

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

E /

SR STAFF SGT WEE SHUN

QIANG, JOSEPH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/06/2023 12:12

Officer In Charge Of Case:

TP / AEIT /

SSI TAY CHUN KEEN

Contact No.: 65476436

Classification Of Case: