

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBQ 3088 P**

Our Ref: PA/FBQ3088/0623/pw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Front centre "V" panel <i>X/M</i>	1 pc	Hdr cracked	155.00	155.00 <i>X</i>
2	Front body cowling LH/RH @ 117.50/-	1 1/2 pcs	Cracked LH	235.00	117.50 <i>✓</i>
3	Body side cowling inner panel LH (mat black)	1 pc	Cracked LH	108.60	108.60 <i>✓</i>
4	Front signal @ \$86/-	12 pcs	Cracked LH	172.00	86.00 <i>75</i>
5	Front fork @ \$480/- <i>@ 337</i>	2 pcs	Bent	960.00	960.00 <i>798</i>
6	Fork under bracket complete <i>X/M</i>	1 pc	Distorted	210.00	210.00 <i>X</i>
7	Front mudguard <i>repair</i>	1 pc	Cut	110.00	110.00 <i>X</i>
8	Fender inner panel	1 pc	Cracked	185.80	185.80 <i>✓</i>
9	Foot board LH	1 pc	Cracked	185.50	185.50 <i>✓</i>
10	Footrest board lower side cover LH	1 pc	Cracked	128.60	128.60 <i>✓</i>
11	Side centre cover LH	1 pc	Cut	115.80	115.80 <i>✓</i>
List price less discount 10%				2,567.30	2,363.80
				256.73	236.38
				2,310.57	2,127.42
<i>1715.80</i>					
<i>1544.22</i>					
<i>1544.22</i>					
12	<u>Add special net item</u>	1 set	Necessary	180.00	90.00 <i>60</i>
13	Steering cone bearing	1 set	Necessary	180.00	180.00 <i>120</i>
14	Body sticker	1 set	Deformed	220.00	220.00 <i>150</i>
Aluminium footboard step				580.00	460.00

Labour Charges
Towing (2 trips) *1190*
Chassis frame repair & align *1200 40*
Remove & replace accident damage parts *5500 200*
5000 250

Total parts & labour concluded *4,290.57 3,757.42*
Lump sum repair adjustment *3,000.00*

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBQ 3088 P**

Our Ref: PA/FBQ3088/0623/pw

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to be returned.

[Signature]
Prudent Adjustors Services
Bok Lee Tan

1544.22
330.00
1190.00
3064.22
206
2451.37
415.21450
3000