



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23006254/Rvy3m4	
			Date: 18/07/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5135G	Veh. Inspected	FBQ 3088P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/23/2035	Excess (\$)	0.00
	Assign From	ANA	Assign Date	20/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA AEROX GDR155A	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3SG4640KJ056689	Colour	BLUE
	Odometer	75496 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	110/80-14	PIRELLI	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70-14	PIRELLI	4 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	15/06/2023	Inspection Date	21/06/2023
	Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	