

ASS. REC. BY: Marcus

REF:

CS/AG/23006255/4943

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMW 8463at Workshop m/s Pacific

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$54k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or NoLump Sum: 10.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

307d

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LIA 24961Veh No: SMW 8463Yr Regn: 23/05/16Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA/ R-LINEMake: Volkswagen Golfc.c. 1395Colour: RedA/C: Insured / Std / NI / NASp. Reading: 160845T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVWZZZAUZG W271247Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40 R18

M.C.

R: \_\_\_\_\_

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/05/23D.O.I. 4/7/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

207 15k.01 say No Damage9/2 \$800 (No lump sum)inbound you have credit #3639-17, 827.2

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 800 )

# PRECISE AUTO SERVICE

NO.1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO.REG.NO.: 35766600C

GST REG. NO.: 35766600C

23-07-23

Accident Date : 28-05-2023

Marcus

OUR REF. : SMW 846B/T/23

Haslinda Binte Mohamed Said

Blk 812C Choa Chu Kang Ave 7

#07-623

Singapore 683812

Date in/out: 04/07/23 to 06/07/23

not Arthur  
her

4/7/23

1/p \$800 2 days

**ESTIMATE BILL ON VEH. NO. : SMW 846B**

**VEH. MODEL : VOLKSWAGEN GOLF**

**CHASSIS NO. : WVWZZZAUZGW271247**

## LIST ITEM

|                              |              |    |          |   |
|------------------------------|--------------|----|----------|---|
| Rear Bumper                  |              | 12 | 1,550.00 | X |
| Rear Bumper Side Retainer RH |              | 11 | 85.00    | X |
| Rear Bumper Clips            | 10pcs @ 7.11 | 11 | 71.10    | X |
| Rear Wheel Bearing Hup RH    |              | 12 | 620.00   | X |
|                              |              |    | 2,326.10 |   |
| Less Discount 10%:           |              |    | 535.76   |   |
|                              |              |    | 1,790.34 |   |

## SPECIAL NETT ITEM

|                          |    |        |   |
|--------------------------|----|--------|---|
| Sport Rim Assy (Rear RH) | 12 | 850.00 | X |
|--------------------------|----|--------|---|

## LABOUR CHARGE

|                                                                                  |    |        |     |
|----------------------------------------------------------------------------------|----|--------|-----|
| To remove & refix rear RH sport rim & contact wheel balancing                    | 11 | 120.00 | X   |
| To remove & refix rear wheel bearing hup                                         | 12 | 180.00 | X   |
| To check & refic computer wheel alignment                                        |    | 120.00 | 60  |
| To respray affected areas                                                        |    | 550.00 | 500 |
| To renew damaged parts, straighten & repair rear RH fender and aligned all parts |    | 500.00 | 240 |

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GST 8%  
TOTAL AMOUNT :

4,110.34

328.83

4,439.17