COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHC3681D

MAKE

REG. 21.10.2019

16.06.2023

CHIANG/INCOME

DEL	IONIQ G3				
Qty	Parts Description/ Labour		Type		Amount
	1 REAR BUMPER				Le \$459.40
:	REAR BUMPER SIDE BRACKET LH/RH	l		\$55.80	5111.60
10	REAR BUMPER CLIPS			\$2.20	per \$22.00
	REAR BUMPER CENTRE MOULDING				de \$451.25
	REAR BUMPER LOWER CENTRE MOULDING				\$155.00
1	REAR BUMPER REINFORCEMENT			Nu.	\$394.80
	REAR REINFORCEMEN STAY LH/RH		I	\$138.10	又 \$276.20
1	REAR BUMPER FOG LAMP				s201.50
1	REAR SMART KEY SENSOR			ι	₩ X \$40.50
1	REAR BUMPER NUMBER LAMP			· c	[^] [^] [↑] \$85.30
1	TOWING COVER	ĺ			\$98.80
		SUB TOTAL		1232 .95	\$2,296.35
	i	20.00%		986, 5 5	\$459.27
	DISCOUNTED TOTAL				\$1,837.08
1	REAR NUMBER PLATE W/HOLDER				1
	REAR REVERSE SENSOR	LKK Auto Co		nce notify	\$55.00
	REAR BUMPER MAT	the Repairer t To resurvey be		painting	\$180.00-
-	NEW COMMENTAL	To display dam	aged part(s) di	ring resurvey	\$50.00
		Parts prices are Third party sup-		firmation hout Prejudice" basis	\$261.50
	Labour Charge	No itiegal modi			
	Panel Beating	Supplementary	item(s) must t	e resurveyed <u>and</u> m Insurance Company	
TI CONTRACTOR OF THE CONTRACTO	Spray Painting Charge	is sucject to in	ai abbiossi iio	11 insurance company 2	\$600.00
	Check Wiring and Lighting	Acknowledged b	y Repairer		250 \$400.00
	Remove/refix Reverse sensor	Signas ma: Date:		660	\$60.00
				10:	ラン \$60.00
Ì	TOTAL LABOU			1913.36	\$1,120.00
ł	FCTIA	AATE TOTAL		1154 500	
Ì	ESTIMATE TOTAL			1200	\$3,218.58
	is is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	e prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				
	appointed by the insurance company.				

toufmi eryegstreg ver lelbler ett 5 ([s Rosing off peper -2 days tenfle e leharden