

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 20.06.2023

MODEL: Hyundai Ioniq

VEHICLE NO.: SHC3130C

SMC8719M

INSURANCE: INCOME CLS

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 481.10 <i>de</i>
	Front Bumper Upper Moulding	1		\$ 368.50 <i>at</i>
	Front Bumper Clips	10	\$ 2.20	\$ 22.00 <i>re</i>
	Front Bumper Side Brkt RH	1		\$ 35.00 <i>de</i>
	Front Wheel Cap RH	1		\$ 346.40 <i>at</i>
	Front Fender RH	1		\$ 588.80 <i>re</i>
	Front Fender (Blue-Drive) RH	1		\$ 26.60 <i>re</i>
	Front Fender Shield RH	1		\$ 164.70 <i>de</i>
	HeadLamp RH	1		\$ 2,110.30 <i>x nn</i>
	DayLight RH	1		\$ 642.50 <i>x nn</i>
	DayLight Grille RH	1		\$ 93.45 <i>x nn</i>
	SUB TOTAL			\$ 4,879.35
	LESS 20%			\$ 975.87
	TOTAL SPARE PARTS			\$ 3,903.48
	Labour Charge			
	Panel Beating			\$ 800.00 <i>850</i>
	Spray Painting			\$ 600.00 <i>500</i>
	Check Wirings			\$ 40.00 <i>x</i>
	Tuff Kote			\$ 60.00 <i>x</i>
	Wheel Alignment			\$ 120.00 <i>80</i>
	<i>Tanpin 97495749 2 days</i>			
	<i>wp 20/6/23 @ 4pm</i>			
	<i>cls Reming after repair</i>			
	<i>Tanpin C (handover)</i>			
	TOTAL LABOUR			\$ 1,620.00
	ESTIMATE TOTAL			\$ 5,523.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Hyundai Ioniq

Date/Time: 20.06.2023 13:42

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5900945

JC NO305558209

MEMER

COMFORT TRANSPORTATION PTE LTD

MEMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

UNT CARD NO.

REGN NO.:

SHC3130C

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

20.06.2023 09:10

DATE/TIME IN

YR OF MANU.

26.06.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164437

COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 19.06.2023

TURE: 3P 19.06.2023

NO


0010

LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHC3130C-TP



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHC3130C

LIMITS

Vehicle No.:

SHC3130C

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard