



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22007341/Rny3e2-1 Date: 05/07/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SMX 7053X	Veh. Inspected	SNE 7723J	
Policy No.	DMPCSNW00015032201	Coverage (\$)	0.00	
Claim No.	SNM22D205353/C02/IRENE	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	20/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD 7-SEATER 2.5	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	AGH300377815	Colour	BLACK	
Odometer	66226 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R16	TOYO	6 mm	
L/H Front Tyre	215/50 R16	TOYO	6 mm	
R/H Rear Tyre	215/50 R16	TOYO	6 mm	
L/H Rear Tyre	215/50 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	29/07/2022	Inspection Date	22/06/2023	
Survey held at	TT MOTORSPORT PTE LTD 48 TOH GUAN ROAD EAST #01-103 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	