



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/LPC22007839/Dqy3-1

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22007839/43~~  
Date: ~~16/08/2022~~ 20/06/2023  
Code: LPC2

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 9463H	Veh. Inspected	GZ 3637Z
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC00/026156	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	<del>16/06/2022</del> 20/06/2023

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	15/08/2022	Inspection Date	
Survey held at	TAN ENG HUAT MOTOR BLK 6 DEFU LANE 10 #01-556 . SINGAPORE 539187		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.