



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22007839/Dqy3m4-1

Date: 23/06/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 9463H	Veh. Inspected	GZ 3637Z
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC00/026156	Excess (\$)	0.00
Assign From	CHARMAINE KONG	Assign Date	20/06/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA REGIUS 2.5	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	KDH2000012974	Colour	WHITE
Odometer	465629 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	195 R15	OHTSU	6 mm
L/H Rear Tyre	195 R15	OHTSU	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/08/2022	Inspection Date	17/08/2022
Survey held at	TAN ENG HUAT MOTOR BLK 6 DEFU LANE 10 #01-556 . SINGAPORE 539187		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**