

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Jul 2023)	
<b>Parts:</b>	N/A	NISSAN NV350 URVAN 2.0 5AT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL9335M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT RH CORNER PANEL	10.00	0.00	*587.00 FL
2	1		*FRONT INNER PANEL	10.00	0.00	*1,043.00 FL
3	1		*AIRCOND BLOWER ASSY	10.00	0.00	*950.00 FL
4	1		*AIR DUCT RH	10.00	0.00	*142.00 FL
5	1		*COOLING COIL BOX ASSY	10.00	0.00	*2,770.00 FL
6	1		*AIRCON PIPE FROM COOLING COIL TO DRYER	10.00	0.00	*140.00 FL

F=Franchise part. L=ListItemDisc.

**Sub Total (S\$)** **5,632.00**

**- List Item Discount on L Items (S\$)** **563.20**

**Total Parts (S\$)** **5,068.80**

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**



Search



ENG  
US