

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0585/2023/EQ
DATE : 21-Jun-23
WIP : 25757

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/6/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : DR NG CHOON YONG
ADDRESS : 15 TONG WATT ROAD
#13-12, WHARF RESIDENCE
SINGAPORE 238026
TELEPHONE : HP +65 96900827
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100402824-08
VEHICLE NO : **SKR 5540 A**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 13/2/2015
ENGINE NO : CZC 226136
CHASSIS NO : WAUZZZ8V2F1076059
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jun-23
PLACE OF ACCIDENT : PIE IN THE DIRECTION OF CHANGI, 100M BEFORE EXIT TO
SIMS AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 5540 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	
3	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	600.00	
4	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
TOTAL LABOUR CHARGES		:	\$	3,160.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 5540 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
8	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	
9	TO DISMANTLE AND RENEW REAR BUMPER, REAR LID AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,300.00	
10	TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, RHS SILL PANEL, RHS REAR DOOR, ROOF CHANNEL, DOOR ENTRANCES, DRAIN CHANNEL AND REAR END PANELLING	\$	6,500.00	
11	TO RENEW RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 18,422.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5540 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,328.00	
2	REAR BUMPER FIXING PARTS	1	\$ 213.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 38.00	
4	REAR BUMPER LOCKING MECHANISM	1	\$ 36.00	
5	REAR BUMPER SPOILER	1	\$ 279.00	
6	REAR BUMPER REFLECTOR - RH	1	\$ 49.00	
7	REAR OUTER TAIL LIGHT - RH	1	\$ 1,030.00	
8	REAR OUTER TAIL LIGHT TRIM - RH	1	\$ 36.00	
9	REAR INNER TAIL LIGHT - RH	1	\$ 1,030.00	
10	REAR INNER TAIL LIGHT TRIM - RH	1	\$ 36.00	
11	REAR BUMPER SIDE REINFORCEMENT	1	\$ 680.00	
12	REAR BUMPER BRACKET - LH / RH	2	\$ 32.00	
13	REAR BUMPER GUIDE SECTION - RH	1	\$ 79.00	
14	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
15	REAR PARKING AID SEAL RING	4	\$ 11.00	
16	REAR BUMPER WIRING SET	1	\$ 578.00	
17	REAR LID	1	\$ 3,869.00	
18	REAR LID ATTACHMENT PARTS	1	\$ 326.00	
19	REAR LID FLAP GASKET	1	\$ 242.00	
20	REAR LID LOCK	1	\$ 217.00	
SUB TOTAL SPARE PARTS		:	\$ 11,652.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5540 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK COVER	1	\$ 9.00	
22	PACKING ADHESIVE	1	\$ 22.00	
23	AUDI EMBLEM	1	\$ 152.00	
24	"A3" INSCRIPTION	1	\$ 110.00	
25	"TFSI" INSCRIPTION	1	\$ 110.00	
26	REAR SIDE PANEL - RH	1	\$ 4,706.00	
27	REAR WINDOW	1	\$ 961.00	
28	REAR QUARTER WINDOW	1	\$ 773.00	
29	WINDOW PRIMER	2	\$ 47.00	
30	REAR DOOR SILL TRIM STRIP - RH	1	\$ 81.00	
31	REAR WHEEL HOUSING LINER	1	\$ 281.00	
32	REAR VENT TRIM	1	\$ 77.00	
33	REAR FUEL INSERT	1	\$ 106.00	
34	REAR DOOR - RH	1	\$ 3,456.00	
35	REAR DOOR OUTER SEAL - RH	1	\$ 189.00	
36	BONDING AGENT	1	\$ 51.00	
37	CLEANING SOLUTION	1	\$ 80.00	
38	APPLICATOR	1	\$ 9.00	
39	REAR DOOR ATTACHMENT PARTS	1	\$ 142.00	
40	REAR DOOR CATCH - RH	1	\$ 122.00	
SUB TOTAL SPARE PARTS		:	\$ 11,484.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5540 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR ALUMINIUM RIM - RH	1	\$ 1,380.00	
42	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
43	1/4 GLASS SEALANT	S/N	\$ 100.00	
44	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
45	ACRYLIC SEALANT	S/N	\$ 180.00	
46	CAVITY WAX	S/N	\$ 140.00	
47	STONE CHIP	S/N	\$ 180.00	
48	METAL FILLER POWDER	S/N	\$ 280.00	
49	RHS REAR TYRE	S/N	TBC	
50	SUNDRIES		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 26,300.00	
TOTAL LABOUR CHARGES		:	\$ 18,422.00	
GRAND TOTAL		:	\$ 44,722.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT