

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hiew, Chasin

Date: 26 Jun 2023

**Preliminary Advice**

Vehicle No	: SKR5540A	Accident Date	: 20/06/2023
Make	: AUDI A3	Policy No.	: 2100402824
Assignment Date	: 21/06/2023	Excess	: S\$600.00
Date of Inspection	: 23/06/2023	Est. Duration of Repair	: 14
Inspection At	: PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,722.00
Revised Amount	:S\$	27,543.00
Check Items (Estimated)	:S\$	2,304.00
Total	:S\$	29,847.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	18,411.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,589.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PENDING REPAIR COST FROM REPAIRER.