



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SJK9726D TOYOTA RUSH

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 980.00 <i>de</i> ✓
2	1	Rear bumper left bracket	\$ 88.00 <i>X</i>
3	1	Rear bumper right bracket-bigger	\$ 98.00 <i>de</i> ✓
4	1	Rear bumper left retainer	\$ 68.00 <i>de</i> ✓
5	1	Rear bumper right retainer	\$ 68.00 <i>X</i>
6	1	Rear bumper tow cover	\$ 88.00 <i>X</i>
7	2	Bumper refelctor	\$ 200.00 <i>X</i>
8	1	Rear tailgate rubber garnish	\$ 372.20 <i>cut</i> ✓
9	1	Rear boot assy	\$ 1,893.20 <i>bt</i> ✓
10	1	Rear tailgate emblem TOYOTA and Rush	\$ 165.00 <i>re</i> ✓
11	1	Rear tailgate lock assy	\$ 285.00 <i>bt</i> ✓
12	1	Look hook	\$ 95.00 <i>X</i>
13	1	Rear tailgate middle chrome	\$ 375.00 <i>X</i>
14	1	Tailgate door handle	\$ 198.00 <i>X</i>
15	1	Rear tailgate no plate lamp	\$ 95.00 <i>X</i>
16	1	Tailgate light left	\$ 550.00 <i>cut</i> ✓
17	1	Tailgate light right	\$ 550.00 <i>X</i>
19	2	Rear tailgate damper	\$ 380.00 <i>X</i>
20	1	Rear end lower panel	\$ 850.00 <i>Ry</i>
21	1	keyless antenna and holder assy	\$ 380.00 <i>X</i>
23	1	Rear end panel top garnish	\$ 190.00 <i>de</i> ✓
24	1	Spare wheel tyre with rim	\$ 450.00 <i>X</i>
25	1	Spare wheel carrier assy	\$ 550.00 <i>bt</i> ✓
26	1	Windscreen	\$ 750.00 <i>bno</i> ✓
27	1	Wiper motor	\$ 550.00 <i>bt</i> ✓
28	1	Wiper arm	\$ 350.00 <i>cut</i> ✓
29	4	Spare wheel mountings	\$ 240.00 <i>dis</i> ✓
Sub-total Parts			\$ 10,608.40



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

TOYOTA SLC3930M WISH

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	80.00 3000 ✓
2	6	Rear end lower panel top garnish clips	\$	50.00 200 ✓
3	1	Rear end lower panel sealant	\$	120.00 X
4	8	Rear tailgate inner trim board clips	\$	50.00 X
5	6	Rear tailgate outer garnish clips	\$	50.00 X
6	1	Rear windscreen glass sealant	\$	80.00 500 ✓
7	3	Rear windscreen mounding	\$	300.00 1000 ✓
8	10	Spare wheel carrier clips	\$	80.00 X
9	1	Rear bumper reverse sensor	\$	2000 300.00 nu ✓
10	1	Rear no plate with garnish	\$	80.00 X
11	1	Rear end camera	\$	450.00 X
12	1	Body Sticker	\$	500.00 250
13	1	Bicycle rack	\$	650.00 600 - 300
Sub total special nett			\$	2,790.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SJK9726D

Modle: TOYOTA RUSH

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 50
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 2,500.00 6700
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel and side panel, and rear fender	\$ 2,500.00 700
5	Carry out wheel alignment	\$ 120.00 X
6	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00 60
7	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00 60
8	Checking central lock system for proper function	\$ 120.00 X
9	Removing and installing rear fender internal garnish and trimming to facilitate the necessary repair	\$ 120.00 X
10	Removing and installing rear window /windscreen glass	\$ 150.00 120
11	To remove and install rear camera	\$ 80.00 X
12	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00 X
13	Water test after accident repair body work	\$ 120.00 X
14	Removing and install keyless antenna and check for proper function	\$ 120.00 X
15	Carry out diagnosis check including cleaning accident fault code	\$ 150.00 X
16	To remove and install rear spare wheel assy	\$ 150.00 X
17	To remove and install bicycle rack	\$ 150.00 X
Total labour :		\$ 6,980.00

Tanpin 97475749
 'wp' 21/8/73
 LKs Resing after repair
 15 days
 Tanpin @ Khandu.com

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: