

Not Authorized
 L/Ry &
 Recovery After Paint
 5 days

Vehicle Insured : SLM 9011 Z
 Accident Date : 20-May-2023

No. : 32948

Date : 26-May-2023

Our Ref : 023293 (ALLIANZ) / JADE

PAGE : 1

MOHAMED KASSIM BIN ABDUL RAHIM (MR)
 Singapore

ESTIMATED COST OF REPAIR FOR CITROEN GRAND C4 PICASSO 1.6 (2016) SMU7654C

1 pc front bumper		CM 2,350.00 ✓
1 pc front bumper side retainer set		270.00
1 pc front bumper towing cover		RM 68.00 X
2 pcs front bumper fog lamp (LH/RH)	@ S\$150.00	RM 300.00 X
2 pcs front bumper fog lamp cover (LH/RH)	@ S\$240.00	RM 480.00 X
1 pc front bumper lower centre grille		RM 600.00 ✓
1 pc front bumper lower centre grille chrome moulding		RM 300.00 ✓
1 pc front bumper lower centre grille side cover		RM 75.00 X
1 pc front bumper lower centre grille inner air guide		RM 90.00 X
1 pc front bumper lower bracket set		270.00 ?
1 pc front bumper reinforcement		750.00 ?
1 pc front bumper centre bracket		CM 600.00 ✓
1 pc front bumper top bracket		500.00
1 pc front bumper undercover		600.00
1 pc front grille		CM 190.00 ✓
1 pc front grille chrome moulding set		RM 280.00 ✓
2 pcs headlamp (LH/RH)	@ \$1300.00	2,600.00 ?
2 pcs front bumper light (LH/RH)	@ S\$600.00	1,200.00 ?
2 pcs front bumper light chrome moulding (LH/RH)	@ S\$300.00	RM 600.00 X
2 pcs front bumper light chrome moulding bracket (LH/RH)	@ S\$250.00	RM 500.00 X
2 pcs front fender (LH/RH)	@ S\$900.00	RM 1,800.00 X

Press any key to continue...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Road #02-18/19/20

Sin Ming Road City

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SLM 9011 Z
Our Ref : 023293

Page : 2
No. : 32948

2 pcs front fender inner shield (LH/RH)	@ S\$300.00	h	600.00	X
1 pc front support panel		CM	420.00	✓
2 pcs front support panel side panel (LH/RH)	@ S\$200.00	Bu	400.00	✓
2 pcs front support panel air guide (LH/RH)	@ S\$200.00		400.00	?
1 pc front support panel top garnish		CM	180.00	✓
1 pc bonnet		Ry	1,500.00	✓
2 pcs bonnet hinges (LH/RH)	@ S\$225.00	R	450.00	X
1 pc bonnet lock		D17	240.00	✓
1 pc bonnet lock catch		D17	200.00	✓
1 pc bonnet safety lock			220.00	?
1 pc bonnet insulator		h	370.00	X
10 pcs bonnet insulator clips	@ S\$ 8.00	m	80.00	X
1 pc bonnet lock cable			240.00	?
1 pc bonnet stand		R	170.00	X
1 pc bonnet stand bush		h	60.00	X
1 pc bonnet stand clip handle		h	60.00	X
1 pc air intake duct			300.00	?
1 pc air intake duct hose			330.00	?
1 pc air intake duct base			200.00	?
1 pc aircon condenser			450.00	?
1 pc aircon condenser liquid pipe		h	720.00	X
1 pc aircon condenser suction pipe		h	720.00	X
1 pc aircon condenser discharge pipe		h	870.00	X
1 pc radiator		h	750.00	X
1 pc radiator fan assy		h	600.00	X
			24,953.00	
Less 10% :			-2,495.30	
			22,457.70	
1 pc front number plate		CM	40.00	sn ✓
1 pc radiator coolant		m	48.00	sn 3000

Con't Page 3 ...

金興(豐)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

500, Seong Ming Drive #02-18/19/20

Seong Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SLM 9011 Z
Our Ref : 023293

Page : 3
No. : 32948

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1,100.00 *600*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *20*

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00 *✓*

To putty and respray on affected
portions.

1,200.00 *600*

Total : S\$24,995.70

Singapore Dollars TWENTY FOUR THOUSAND NINE HUNDRED
NINETY FIVE AND CENTS SEVENTY Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: