



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS3/FCI23006287/y3

Date: 21/06/2023

Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMP 9227R	Veh. Inspected	GBJ 8972R
Policy No.		Coverage (\$)	0.00
Claim No.	D23002020MFZH	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	21/06/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/03/2023	Inspection Date	
Survey held at	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.