

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :**Date of Survey :****Date of ReSurvey:****Contacts :****Vehicle Nos : GBE 8643S****Made :** Nissan**Model :** NV350 Panel Van**Chassis No :***** AGREED Cost Of Repair and Repair Day/s with SJE *****Amount:****Working Day:**

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper	1	\$ 667.20	\$ de 667.20
2	Rear Bumper Step Panel	1	\$ 269.60	\$ de 269.60
3	Rear Bumper Side Retainer RH	1	\$ 17.40	\$ de 17.40
4	Rear Bumper Side Retainer LH	1	\$ 17.40	\$ X 17.40
5	Rear Tailgate	1	\$ 50% 2,101.40	\$ bt 2,101.40
6	Rear Tailgate Damper RH	1	\$ 175.40	\$ X 175.40
7	Rear Tailgate Damper LH	1	\$ 175.40	\$ X 175.40
8	Rear Tailgate Outer Chrome Moulding	1	\$ 463.90	\$ X 463.90
9	Rear Tailgate Emblem	1	\$ 64.90	\$ de 64.90
10	Rear Tailgate "NV350" Emblem	1	\$ 110.00	\$ de 110.00
11	Rear Tailgate "Urvan" Emblem	1	\$ 78.90	\$ de 78.90
12	Rear Tailgate Weatherstrip	1	\$ 269.30	\$ X 269.30
13	Rear Tailgate Outer Key Lock	1	\$ 278.40	\$ X 278.40
14	Rear Tailgate Number Plate Lamp RH	1	\$ 48.30	\$ X 48.30
15	Rear Tailgate Number Plate Lamp LH	1	\$ 48.30	\$ X 48.30
16	Rear Tailgate Inner Lock	1	\$ 394.10	\$ X 394.10
17	Rear Tailgate Inner Lock Motor	1	\$ 267.30	\$ X 267.30
18	Rear Tailgate Inner Trim	1	\$ 298.40	\$ X 298.40
19	Rear Tailgate Windscreen Glass	1	\$ 1,396.90	\$ X 1,396.90
20	Rear Taillamp Assembly RH	1	\$ 298.70	\$ Curr 298.70
21	Rear Taillamp Assembly LH	1	\$ 298.70	\$ X 298.70
22	Rear Taillamp Panel RH	1	\$ 233.60	\$ X 233.60
23	Rear Taillamp Panel LH	1	\$ 233.60	\$ X 233.60
24	Rear End Panel Outer	1	\$ 461.60	\$ Ex 461.60
25	Rear End Panel Inner	1	\$ 568.40	\$ X 568.40
26	Rear Floor Panel	1	\$ 1,883.20	\$ X 1,883.20
27	Rear Floor Panel Mat	1	\$ 981.60	\$ X 981.60
28	Rear Fender RH	1	\$ 2,644.20	\$ X 2,644.20
29	Rear Fender LH	1	\$ 2,644.20	\$ X 2,644.20
30	Spare Tyre Chain	1	\$ 294.70	\$ X 294.70
31	Spare Tyre Chain Support Member	1	\$ 387.60	\$ X 387.60
32	Spare Tyre Chain Pipe	1	\$ 189.80	\$ X 189.80

33	Rear Exhaust Pipe	1	\$	890.50	\$ X	890.50
Parts Sub Total :					\$	19,152.90
10% Discount					\$	1,915.29
PARTS TOTAL :					\$	17,237.61

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ X 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30.00 50.00
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ X 50.00
4	Rear Tailgate Outer Garnish Clips - Set	1	\$ 30.00	\$ X 30.00
5	Rear Tailgate Inner Trim Clips - Set	1	\$ 50.00	\$ X 50.00
6	Rear Tailgate Windscreen Glass Sealant	1	\$ 150.00	\$ X 150.00
7	Rear Tailgate "70km/h" Sticker	1	\$ 50.00	\$ 49-30 50.00
8	Rear Tailgate "8 Pax" Sticker	1	\$ 50.00	\$ 49-30 50.00
9	Rear Tailgate Sealant	1	\$ 150.00	\$ X 150.00
10	Rear End Panel Sealant	1	\$ 150.00	\$ X 150.00
11	Rear Floor Panel Sealant	1	\$ 300.00	\$ X 300.00
12	Rear Fender RH Sealant	1	\$ 150.00	\$ X 150.00
13	Rear Fender LH Sealant	1	\$ 150.00	\$ X 150.00
14	Rear Fender Advertisement Sticker RH	1	\$ 800.00	\$ X 800.00
15	Rear Fender Advertisement Sticker LH	1	\$ 800.00	\$ X 800.00
16	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 200.00 250.00
17	Rear Tailgate Reverse Camera	1	\$ 500.00	\$ X 500.00
SPECIAL NETT TOTAL :				\$ 3,730.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 500 2,400.00
2	To Spray Paint Affected Areas	\$ 600 1,800.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120 150.00
5	To Transfer Rear Tailgate Mechanism	\$ 60 150.00
6	To Remove & Refix Rear Tailgate Reverse Camera	\$ 30 150.00
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30 120.00
8	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ X 150.00
9	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 200.00
10	To apply anti rust on affected parts	\$ 30 250.00
11	To Conduct Water Leak Test	\$ X 100.00
12	To Send for Diagnostic and Reset Control Unit, Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 6,050.00

Tanjinh 97495741 - 4 days
 WP' 5/7/23 @ 340pm
 L/S Resurvey after repair
 tanjinh@lkhaut.com
 - To check consistency of accident
 - To check part prices

LKH Auto Consultants hence notify the Repairer of the following:
 SPECIAL NETT TOTAL: \$ 3,730.00
 LABOUR TOTAL: \$ 6,050.00
GRAND TOTAL: \$ 27,017.61
 Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature: _____
 Date: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	396G
Vehicle Details	
Vehicle No.:	GBE8643S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jul 2023
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	YD25389037A
Chassis No.:	JN1MC2E26Z0005937
Maximum Power Output:	-
Open Market Value:	\$22,153.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$1,108.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	06 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,001.00
COE Rebate Amount:	\$12,412.00
Total Rebate Amount:	\$12,412.00

The information contained herein is correct as at 03 Jul 2023

OK