



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/06/2023
Vehicle Reg. No.:	SGX6092K	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	30/08/2007
Vehicle Colour:	BEIGE	Chassis No:	MR053HY9305015595
Engine No:	1NZX588702		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	830.50
Miscellaneous Items	0.00
Labour	840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,670.50
+ GST 8.00% (\$)	133.64
Nett Amount (\$)	1,804.14

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS	
Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 20 Jun 2023)
Parts:	143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX6092K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP ASSY LH	0.00	0.00	*250.00 F
2	1		*FRONT BUMPER	0.00	0.00	*250.00 F
3	1		*FRONT BUMPER LOGO	0.00	0.00	*45.00 F
4	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*45.00 F
5	10		*FRONT BUMPER CLIPS	0.00	0.00	*25.00 F
6	1		*FRONT LAMP GARNISH LH	0.00	0.00	*95.00 F
7	1		*FRONT FENDER LH (REPAIR)	0.00	0.00	-
8	1		*FRONT FENDER EMBLEM - VVT-I	0.00	0.00	*45.00 F

F=Franchise part.

Sub Total (\$\$)	755.00
+ Margin on L,N Items 10.00% (\$\$)	75.50
Total Parts (\$\$)	830.50

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS
--

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN FRONT FENDER LH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	400.00
2	SPRAY PAINT FRONT BUMPER, FRONT FENDER LH	New	400.00
3	CHECK WIRING & FOCUS HEADLIGHT	New	40.00
Gross Labour Cost (\$\$)			840.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >