

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 26 Jun 2023

Preliminary Advice

Vehicle No	: SMS9897R	Accident Date	: 19/06/2023
Make	: VOLKSWAGEN BEETLE CABRIOLET	Policy No.	: SP2004844242
Assignment Date	: 21/06/2023	Excess	: S\$0.00
Date of Inspection	: 23/06/2023	Est. Duration of Repair	: 3
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,026.36
Revised Amount	:S\$	3,188.82
Check Items (Estimated)	:S\$	1,455.05
Total	:S\$	4,643.87
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	133,000.00
COE / PARF Rebate	:S\$	41,879.00
Salvage Value	:S\$	
Margin for Repair	:S\$	91,121.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.