

(08/11/13) wef

ASS. REC. BY: /

Tayfiker

REF:

CS/LIP23006313/Tqp3

UP.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD SES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$104K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

David

Veh No: SMK4716E Yr Regn: 2011 April

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 310603 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD ES 3E4025040541

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Finny 9.

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 16/6/23

Survey held at My Car Consultants

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S, U/C, N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Revised: 043083

No # Value: 060917

03/07/23 Stewart informed they rejected the claim by email.

03/07/23 Submit Preli. report

Date/Time, File Pass to?



Preli. Report

1) 03/07 Typist



Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____).



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896
HP: 93911482

Estimation

Date: 16/6/2023

Vehicle: SMK4716E

Make / Model: TOYOTA PRIUS

Chassis No: LIBERTY

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:	1		
1	BONNET	1	\$ 1,025.00	\$ 1,025.00
2	BONNET LOCK	1	\$ 312.00	\$ 312.00
3	FRONT BUMPER	1	\$ 798.00	\$ 798.00
4	FRONT BUMPER SIDE RETAINER	2	\$ 112.00	\$ 224.00
5	FRONT BUMPER REINFORCEMENT	1	\$ 412.00	\$ 412.00
6	FRONT BUMPER SPONGE	1	\$ 198.00	\$ 198.00
7	FRONT BUMPER FOGLAMP	2	\$ 312.00	\$ 624.00
8	FRONT BUMPER FOGLAMP COVER	2	\$ 159.00	\$ 318.00
9	FRONT BUMPER LOWER	1	\$ 581.00	\$ 581.00
10	FRONT BUMPER DAYLIGHT	1	\$ 312.00	\$ 312.00
11	FRONT BUMPER LOGO	1	\$ 65.00	\$ 65.00
12	FRONT GRILLE	1	\$ 398.00	\$ 398.00
13	HEADLAMP	2	\$ 2,598.00	\$ 5,196.00
14	FRONT WINDSCREEN GLASS	1	\$ 1,359.00	\$ 1,359.00
15	FRONT WINDSCREEN GLASS MOULDING	1	\$ 198.00	\$ 198.00
16	FRONT WINDSCREEN PILLAR	2	\$ 322.00	\$ 644.00
17	FRONT WINDSCREEN PILLAR INNER TRIM	2	\$ 214.00	\$ 428.00
18	FRONT FENDER	2	\$ 581.00	\$ 1,162.00
19	FRONT FENDER COWLING	2	\$ 198.00	\$ 396.00
20	FRONT FENDER EMBLEM	2	\$ 52.00	\$ 104.00
21	FRONT FENDER QUARTER GLASS C/W MOULDING	2	\$ 387.00	\$ 774.00
22	ENGINE MOUNTING SET	1	\$ 1,985.00	\$ 1,985.00
23	ROOF TOP PANEL SIDE GARNISH	2	\$ 198.00	\$ 396.00
24	ROOF TOP INNER LINER	1	\$ 2,110.00	\$ 2,110.00
25	FRONT DASHBOARD	1	\$ 2,241.00	\$ 2,241.00
26	FRONT DASHBOARD SENSOR	1	\$ 662.00	\$ 662.00
27	REAR VIEW MIRROR	1	\$ 311.00	\$ 311.00
28	SIDE MIRROR	2	\$ 687.00	\$ 1,374.00
29	WIPER WASHER TANK	1	\$ 398.00	\$ 398.00
30	HEADLAMP	2	\$ 2,159.00	\$ 4,318.00
31	AIRCON CONDENSOR	1	\$ 1,125.00	\$ 1,125.00
32	RADIATOR	1	\$ 1,258.00	\$ 1,258.00
33	FRONT CHASSIS EXTENSION RH	1	\$ 352.00	\$ 352.00
34	FRONT DOOR	2	\$ 1,359.00	\$ 2,718.00
35	FRONT DOOR GLASS LH	1	\$ 498.00	\$ 498.00
36	FRONT DOOR PILLAR LH	1	\$ 412.00	\$ 412.00
37	FRONT DOOR OUTER MOULDING LH	1	\$ 112.00	\$ 112.00
38	FRONT DOOR WEATHERSTRIP LH	1	\$ 198.00	\$ 198.00

39	FRONT DOOR INNER LOCK LH	1	\$ 312.00	\$ 312.00	?
40	FRONT DOOR INNER TRIM BOARD	1	\$ 559.00	\$ 559.00	cut
41	FRONT DOOR REGULATOR	1	\$ 587.00	\$ 587.00	?
42	FRONT DOOR GLASS MOTOR LH	1	\$ 689.00	\$ 689.00	?
43	FRONT DOOR FRAME BLACK STICKER SET	1	\$ 215.00	\$ 215.00	ver
44	FRONT DOOR FRAME STEP GARNISH LH	1	\$ 159.00	\$ 159.00	?
45	FRONT DOOR OUTER HANDLE	1	\$ 321.00	\$ 321.00	cut
46	SIDE SKIRTING	2	\$ 1,025.00	\$ 2,050.00	Ry
47	ROCKER PANEL LH	1	\$ 1,125.00	\$ 1,125.00	Ry
48	DOOR CENTRE PILLAR (OUTER) LH	1	\$ 651.00	\$ 651.00	Ry
49	DOOR CENTRE PILLAR (INNER) LH	1	\$ 511.00	\$ 511.00	x nn
50	DOOR CENTRE PILLAR INNER TRIM LH LOWER	1	\$ 215.00	\$ 215.00	x nn
51	DOOR CENTRE PILLAR INNER TRIM LH TOP	1	\$ 211.00	\$ 211.00	x nn
52	FRONT CROSSMEMBER	1	\$ 2,985.00	\$ 2,985.00	?
53	FRONT KNUCKLE ARM	2	\$ 498.00	\$ 996.00	RH 67-
54	FRONT KNUCKLE BEARING	2	\$ 158.00	\$ 316.00	RH 67-
55	FRONT LOWER ARM	2	\$ 512.00	\$ 1,024.00	RH 67-
56	FRONT SHOCK ABSORBER	2	\$ 487.00	\$ 974.00	RH 67-
57	STEERING RACK AND PINION	1	\$ 2,258.00	\$ 2,258.00	?
58	REAR DOOR LH	1	\$ 1,359.00	\$ 1,359.00	bt-
59	REAR DOOR GLASS	1	\$ 498.00	\$ 498.00	?
60	REAR DOOR INNER LOCK	1	\$ 312.00	\$ 312.00	?
61	REAR DOOR INNER TRIM BOARD	1	\$ 559.00	\$ 559.00	?
62	REAR DOOR REGULATOR	1	\$ 587.00	\$ 587.00	?
63	REAR DOOR GLASS MOTOR	1	\$ 689.00	\$ 689.00	?
64	REAR DOOR HINGES BOTTOM	1	\$ 68.00	\$ 68.00	?
65	REAR DOOR FRAME GARNISH	1	\$ 159.00	\$ 159.00	?
66	REAR DOOR FRAME BLACK STICKER	1	\$ 89.00	\$ 89.00	9-
67	REAR DOOR FRAME STEP GARNISH LH	1	\$ 159.00	\$ 159.00	?
68	REAR DOOR OUTER HANDLE	1	\$ 321.00	\$ 321.00	cut
69	REAR FENDER LH	1	\$ 712.00	\$ 712.00	7-
70	REAR FENDER INNER TRIM LH	1	\$ 512.00	\$ 512.00	x nn
71	REAR FENDER COWLING	1	\$ 198.00	\$ 198.00	?
72	REAR FENDER QUARTER GLASS C/W MOULDING LH	1	\$ 398.00	\$ 398.00	cut
73	REAR BUMPER	1	\$ 798.00	\$ 798.00	Ry
74	REAR BUMPER SIDE RETAINER	2	\$ 72.00	\$ 144.00	x nn
75	REAR WHEEL BEARING	1	\$ 212.00	\$ 212.00	?
76	REAR SHOCK ABSORBER RH	1	\$ 398.00	\$ 398.00	x nn
77	TAILAMP LH	1	\$ 512.00	\$ 512.00	cut
	TOTAL PART			\$ 60,838.00	
	LIST DOWN	25%		\$ 15,209.50	
	AFTER LIST DOWN			\$ 45,628.50	
	SPEICAL NETT				
1	BONNET INSULATOR CLIPS	1	\$ 50.00	\$ x 50.00	nn
2	FRONT BUMPER CLIPS SET	1	\$ 50.00	\$ 30 50.00	
3	FRONT DOOR INNER TRIM CLIPS	2	\$ 50.00	\$ 30 100.00	
4	DOOR CENTRE PILLAR INNER TRIM CLIPS SET	1	\$ 50.00	\$ x 50.00	nn
5	FRONT WINDSCREEN SEALANT	1	\$ 80.00	\$ 60 80.00	

6	FRONT WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	✓
7	FRONT SPORTS RIM	2	\$ 800.00	\$ 1,600.00	✓
8	FRONT TYRE	2	\$ 200.00	\$ 200.00	?
9	REAR QUARTER GLASS SEALANT	2	\$ 60.00	\$ 120.00	X nn
10	REAR DOOR INNER TRIM CLIPS	2	\$ 50.00	\$ 100.00	60
11	REAR FENDER INNER TRIM CLIPS SET	1	\$ 50.00	\$ 50.00	X nn
12	SIDE SKIRTING CLIPS	1	\$ 50.00	\$ 50.00	X nn
13	REAR SPORTS RIM LH	1	\$ 800.00	\$ 800.00	✓
14	INTERIOR CAMERA	1	\$ 350.00	\$ 350.00	X nn
TOTAL AMOUNT				\$ 4,400.00	3680
LABOUR					
1	CHECK WIRING	1	\$ 100.00	\$ 100.00	50
2	REMOVE AND REFIR FRT DOOR MECHANISM	2	\$ 80.00	\$ 160.00	120 60
3	REMOVE AND REFIR REAR DOOR MECHANISM	2	\$ 80.00	\$ 160.00	60
4	REMOVE AND REFIR FRONT WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	120
5	REMOVE AND REFIR INTERIOR ROOF LINING	1	\$ 200.00	\$ 200.00	X
6	REMOVE AND REFIR FRONT DASHBOARD	1	\$ 300.00	\$ 300.00	7200
7	REMOVE AND REFIR REAR BUMPER SENSOR	1	\$ 100.00	\$ 100.00	30
8	REMOVE AND REFIR FRONT FENDER QUARTER GLASS	1	\$ 100.00	\$ 200.00	80
9	REMOVE AND REFIR REAR FENDER QUARTER GLASS	2	\$ 100.00	\$ 200.00	X
10	REMOVE AND REFIR UPHOSLETRY SEAT, TO FACIALIATE	1	\$ 400.00	\$ 400.00	100
11	RESET TROUBLE CODE WHOLE SYSTEM	1	\$ 500.00	\$ 500.00	200
12	PANEL BEAT EFFECTED AREAS	1	\$ 3,800.00	\$ 3,800.00	2000
13	RESPARY EFFECTED AREAS	1	\$ 3,800.00	\$ 3,800.00	2000
TOTAL AMOUNT				\$ 10,070.00	
			Parts Replacement Amount	\$ 50,028.50	
			Total Amount for Labour	\$ 10,070.00	
			Total Amount	\$ 60,098.50	59378.50

Tanglin 97415749 / 62563561
 wpt 16/6/23 @ 1145
 LLS Resurvey before paint
 14 days
 - To check repair limit
 - Tanglin @ 1145

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/06/2023 12:03 (SGT)
Reported by	Actual Driver
Date of Accident	08/06/2023 07:15 (SGT)
Exact Location of Accident	Tampines Ave 5, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK4716E

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	LUMENS PTE LTD
Company Reg No	2XXXXX961K
Email Address	kokhow.tay@lumens.sg
Mobile Phone No	(Phone) +65-96170933
Alternative Phone No	(Office) +65-87781765

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	22-MN000812-R00

DRIVER

Name of Driver	ISKHANDAR ZULKARNAIN BIN ABDUL RAHIM
NRIC No	SXXXX973B
Date Of Birth	19/09/1983
Occupation	Outdoor

Date Of Driving Pass	15/12/2003
Driving experience	19 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96170933
Alt. Phone Number	-
Email Address	kokhow.tay@lumens.sg
Address	607 BEDOK RESERVOIR ROAD #03-634
Address complement	-
Postcode	470607
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bedok Division Headquarters
Police Station Phone No	(Phone) +65-18002440000
Alt. Police Station Phone No	(Fax) +65-64443009
Police Station Address	30 Bedok North Road Singapore 469676
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT G/20230610/7031 & G/20230612/7100

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SKZ4478L
Vehicle Manufacturer	Peugeot
Vehicle Model	3008 1.2 EAT8 ACTIVE PREMIUM
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	-
Name of Driver	NA / Unknown
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKT8487R
Vehicle Manufacturer	Subaru
Vehicle Model	SUBARU XV 1.6I-S AWD CVT
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ISKHANDAR ZULKARNAIN BIN ABDUL RAHIM
Gender	Male
Phone No	(Phone) +65-96170933
Address	607 BEDOK RESERVOIR ROAD #03-634
Address Complement	-
Post Code	470607
Approximate Age Years Old	39
Injuries Sustained	-
Injured person in which vehicle?	SMK4716E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN**IMPORTANT NOTICE**

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports, or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (Collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time 11062023 1330HRS

Witnessed by Reporting Centre Personnel



A - SMK4716E

B - SKZ4478L

C - SKT8487R

Describe Circumstances of the Accident

PLEASE REFER TO POLICE REPORT G/20230610/7031

Declaration

We declare the foregoing particulars are true in every respect



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

11062023 1330HRS



**SINGAPORE
POLICE FORCE**



G/20230610/7031

1 of 1

POLICE REPORT (NP299)

Report No. G/20230610/7031

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2440000

Date/Time Report Made 10/06/2023 12:38		Vide Report No.		Station Diary No.	
Name Of Informant ISKHANDAR ZULKARNAIN BIN ABDUL RAHIM		Address 607 BEDOK RESERVOIR ROAD #03-634 SINGAPORE 470607			
ID Type / ID No. NRIC NO / S8328973B		Contact No. Home/Office: Mobile: 96170933			
Nationality SINGAPORE CITIZEN		Email Address iskhandarzulkar@gmail.com			
Occupation Private-hire car driver		Sex Male	Age 39	Date of Birth 19/09/1983	Race Malay
Institution/School Name		Language English			
Date/Time Of Incident 08/06/2023 07:15 - 08/06/2023 08:00		Location Of Incident 1 TAMPINES WALK OUR TAMPINES HUB SINGAPORE 528523			

Brief details.

An accident took place on the road in front of Tampines Hub around 715am. I was taken to CGH by ambulance to assess any injuries.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required
Signature Of Interpreter: Not applicable	Date/Time: 10/06/2023 12:38
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



G/20230612/7100

1 of 2

POLICE REPORT (NP299)

Report No. G/20230612/7100

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2440000

Date/Time Report Made 12/06/2023 18:08	Vide Report No.	Station Diary No.
Name Of Informant ISKHANDAR ZULKARNAIN BIN ABDUL RAHIM	Address 607 BEDOK RESERVOIR ROAD #03-634 SINGAPORE 470607	
ID Type / ID No. NRIC NO / S8328973B	Contact No. Home/Office:	Mobile: 96170933
Nationality SINGAPORE CITIZEN	Email Address iskhandarzulkar@gmail.com	
Occupation Private-hire car driver	Sex Male	Age 39
Institution/School Name	Date of Birth 19/09/1983	Race Malay
Date/Time Of Incident 08/06/2023 07:15 - 08/06/2023 07:30	Location Of Incident 5 TAMPINES CENTRAL 6 TELEPARK SINGAPORE 529482	

Brief details.

Vide report number G/20230608/0052

The accident happened on 8 June 2023, Thursday between 715am -730am along Tampines Ave 5. I was driving in a black Toyota Prius Plus, SMK4716E. I could not recall which lane I was driving on. I was driving straight then my car got hit on the front right side of my car causing my car to flip over to the left.

Signature Of Officer Recording The Report:
Not applicable

Signature Of Informant:
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Signature Of Interpreter:
Not applicable

Date/Time:
12/06/2023 18:08

Officer In-Charge Of Case:

Classification Of Case:

**SINGAPORE
POLICE FORCE**

G/20230612/7100

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20230612/7100

As the car was flipping to its left I frantically unbuckled my seat belt as the belt was biting into the left side of my neck.

I dropped on the passenger side to crawl under via the busted passenger window.

I was temporarily pinned under my car but a passerby rushed to pulled me out.

I was warded for 3 days in CGH.

That is all.

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
12/06/2023 18:08

Classification Of Case: