

GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 4 #02-54/55 PREMIER@KB SINGAPORE 415875 UEN GST REG NO. 202005684D

05th June 2023

Our Ref: SLR4375E Your Ref: SME9251C

HSBC Insurance Singapore Pte Ltd Motor Claims Department 38 Beach Road #03-11, South Beach Tower Singapore 189767

Dear Sirs,

ACCIDENT INVOLVING SLR4375E AND SME9251C ALONG KJE BEFORE PIE CHANGI EXIT ON 28.06.2022

We are the representative for YongSheng E&C Pte. Ltd., whose vehicle registration number **SLR4375E** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SME9251C**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$ 21,168.00
Loss of rental for 11 days @\$180/day	\$ 1,980.00
Survey report	\$ 1,324.00
LTA search fee	\$ 7.45
	\$ 24,479.45

Enclosed are the supporting documents for your perusal:- GIA

Repair bill

Kindly let us have your payment of \$24,479.45 in our workshop's name within the next 14 days.

Please do not hesitate to contact Ms Irene at 6385 1171 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.

GARAGE 13

8 Kaki Bukit Ave 4 Premier @ Kaki Bukit #03-46 Singapore 415875 Company Reg Number: 202005684D

LETTER OF AUTHORISATION

I/We, YONG STENG ERC PRE LTD of NRIC/FIN/UEN NO. 2017/72990, owner M/s GARAGE 13 PTR LTD	of vehicle no. SLR 4375E	("the third party claimant") hereby authorize
		ny claim for repair cost
and/or rental and/or loss of use and/or survey fee ("claim was damaged pursuant to the accident which occurred or		that along
KIE ALONG PIE CHANGI EXIT	involving vehi	icle no/s
SUE 925K	("the accident").	
I further authorize the workshop to settle my above ment workshop is further authorized to receive payment further made in favour of the workshop. I further acknowledge that any settlement the workshop is without admission of liability basis insofar as the driver/or without admission of liability basis insofar as the drivery without admission of liability basis insofar and the drivery without admission of liability basis and the	r to settlement of my claim with p may reach on my behalf is on a wi	payment cheque/s being thout prejudice and
Dated this 39 (day) of 66 (month) 32 (yea	r)	
SIGNATURE OF OWNER/ COMPANY STAMP (IF APPLICABLE)		



MV AUTO SLR 4375E

• RENTAL AGREEMENT & INVOICE •

(MAZDA CX3)

MVA:

| H/P: 91060030

11	SND 9361 K	Model Type	MFRC	P180.	Renting Location	n
Reference		Agreed Retu	rn Date		5 Hours = 1 Day (1 Day Rental / Extension)	
s 180 Per Day	\$ Per	KM			Time/Oate In	2000
\$ Per Week	S Fer	In	\rightarrow $+$	+	Time / Date	7095
S Per Month	Cts Per Kilometer	КМ			Out	
Hires's Name		Out			28/06	5097
Address		KM			Total/Time Cha	argeable
		Driven Rental Charg Total	es Days Ren	tal	Dollars	cents
I /C No. Reference Contact	Tel. No.					
Driver's Name	Passport / IC No.					
Address						
Driving Licence No. Expl Additional Driver	ry Issued by Tel. No. (Home) Passport / IC No. / Country	Out	al E 1/4 1/2	3/4 F in every 1/4, 1/2,	Petrol E 1/4 in	
Driving Licence No. Expir		Others Grand Total Payment Re	eived \$			
Oriving Licence No. Expir Method of Payment LATES QUOTED ARE FOR USE IN SINGA	y Issued by PORE ONLY.	Payment Re	Block Letters)		CASH	CHEQUE
Oriving Licence No. Expir Method of Payment LATES QUOTED ARE FOR USE IN SINGA THE HIRER IS SOLELY RESPONSIBLE FOR RAFFIC LAWS AND ANY PARKING FINE	y Issued by PORE ONLY. BREACH OF	Payment Re By: (Name in	Block Letters) Refundable		CASH	CHEQUE
Address Driving Licence No. Expir Method of Payment MATES QUOTED ARE FOR USE IN SINGA THE HIRER IS SOLELY RESPONSIBLE FOR TRAFFIC LAWS AND ANY PARKING FINE DURING PERIOD OF HIRE. Hirer's signature signifies acceptance of	PORE ONLY. BREACH OF S OF SURCHARGES	Payment Re By : (Name in	Block Letters)	FRONT	CASH	CHEQUE

NB: Please notify our office should there be any accident involving this hired vehicle as soon as possible

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

29 Jun 2022 / 14:29:59

Receipt Date/Time: 29 Jun 2022 / 14:29:59

Tax Invoice/Receipt

Receipt No.: ITNET-00000-220629-002113

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SME9251C As at 28 Jun 2022/09:05:00 Insurance Co: AXA INSURANCE PTE LTD Insurance Enquiry - SME9251C Enquiry Fee		7.00	0.49	7.49
20220629142922327276	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference	1.00	3.10	0.04
	Total Amount Payable			7.45
	Paid By			
	526471XXXXXX2536	eNETS	Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 4 #02-54/55 PREMIER@KB SINGAPORE 415875

UEN GST REG NO: 202005684D

Date

5/6/2023

Proforma Ref No: G13/23117

To

: YongSheng E&C Pte. Ltd.

Vehicle No : SLR4375E


Accident Date: 28/6/2022

PROFORM	IA INVOICE			
Description			Amount	
Repair Cost		\$	19,600.00	
	Sub-Total GST 8% TOTAL	_	19,600.00 1,568.00 21,168.00	

Payment by cheque should be crossed and made payable to 'Garage 13 Pte Ltd'

Issued By:

Authorised Signature



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

22 - 170896

Date:

14/07/2022

INVOICE NO. 170896

YONGSHENG E&C PTE. LTD.

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Registration No.

SLR4375E

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 1,324.00
		Total amount	\$ 1,324.00

Please kindly cross all cheques made payable to "Impact Analysis Consulting Pte Ltd ".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)

Principal Consultant



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170896

Date:

14/07/2022

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 28-06-2022

YONGSHENG E&C PTE. LTD.

In accordance with your instructions received in this office on

30-06-2022

, we made arrangements to

examine the vehicle on

30-06-2022

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Mazda	Registration	SLR4375E
Model	CX-3 XD TOURING 1.5 A/T DIESEL TURBO	Chassis	DK5FW131863
Colour	White	Gearbox	Auto
Odometer	84053km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	225/50R18	75% Westlake
Front right	225/50R18	75% Westlake
Rear left	225/50R18	75% Westlake
Rear right	225/50R18	75% Michelin

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$19,600.00 and 12 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170896

Date

14/07/2022

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items :				
Bonnet	1	buckled	1119.00	1119.00
Bonnet hinge @\$92.40	2	refix	184.80	0.00
Bonnet lock	1	bent	215.00	215.00
Bonnet lock garnish	1	torn	16.90	16.90
Center grille	1	broken	565.80	565.80
Center grille emblem	1	necessary	96.00	96.00
Front bumper chrome garnish	1	broken	268.70	268.70
Front bumper	1	deformed	1195.50	1195.50
Front bumper number plate holder	1	deformed	76.90	76.90
Front bumper side retainer @\$65.80	2	cracked	131.60	131.60
Front bumper signal lamp @\$285.90	2	broken	571.80	571.80
Front bumper signal lamp garnish @\$124.10	2	deformed	248.20	248.20
Front bumper reinforcement	1	bent	598.00	598.00
Front bumper sponge	1	torn	221.00	221.00
Front bumper under cover	1	torn	160.50	160.50
Headlamp @\$1515.00	2	defaced.holder broken	3030.00	3030.00
Front fender outer arch garnish Ih	1	holder torn	166.50	166.50
Front support panel top garnish	1	deformed	114.50	114.50
Front support panel	1	cracked	815.00	815.0
Front support panel baffle	1	deformed	168.80	168.80
Air con condenser	1	dented.twisted	1215.00	1215.0
Tail gate	1	distorted	1635.00	1635.00
Tail gate inner lock	1	bent in.jammed	416.70	416.70
Tail gate hinge @\$78.20	2	refix	156.40	0.00
Tail gate damper @\$205.70	2	bent.stiffened	411.40	411.40
Tail gate emblem 'logo'	1	necessary	115.00	115.0
Tail gate emblem 'CX-3'	1	necessary	82.00	82.00



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170896

Date

14/07/2022

Date	14/07/2022				
Tail gate emblem 'S	SKYACTIV'	1	necessary	92.00	92.00
Tail gate lamp @\$4		2	holder broken	984.60	984.60
Tail gate inner trim		1	torn	367.00	367.00
Tail gate weatherst		1	ripped	256.30	256.30
Tail gate pull holde		1	deformed	32.60	32.60
Tail gate release sw		1	malfunction	148.30	148.30
Tail gate wiper mot	tor	1	bent.malfunction	413.00	413.00
Tail lamp @\$582.9		2	holder broken	1165.80	1165.80
Rear fender inner s	ide trim @\$355.20	2	torn	710.40	710.40
Rear fender arch ga	arnish @\$115.50	2	holder fractured	231.00	231.00
Rear bumper		1	deformed	1207.00	1207.00
Rear bumper side r	atainer @\$50.80	2	cracked	101.60	101.60
Rear bumper reflec	tor @\$167.50	2	cracked	335.00	335.00
Rear blind spot mo	dule lh	1	dented.malfunction	947.40	947.40
Rear blind spot mo	dule bracket Ih	1	torn	70.50	70.50
Rear bumper reinfo	orcement	1	bent	425.00	425.00
Rear bumper lower	bracket @\$106.20	2	torn	212.40	212.40
Rear bumper lower	inner garnish	1	torn	168.70	168.70
Rear bumper lower	inner garnish cover	1	torn	43.40	43.40
Rear number plate	lamp @\$71.80	2	cracked	143.60	143.60
Rear end panel		1	distorted	568.80	568.80
Rear end panel top	garnish	1	deformed	92.00	92.00
Rear floor panel		1	repair.repair	736.40	0.00
Rear floor panel sp	are tyre sponge	1	torn.compressed	324.00	324.00
Rear exhaust silence	er	1	bent	1375.00	1375.00
Rear exhaust heat :	shield	1	deformed	58.00	58.00
		Sub- Tot	al cost	25205.80	24128.20
	Percent	age discount :	20%	5041.16	4825.64
		Sub-Total cos	ts for parts	20164.64	19302.56
Special Nett Items:	i.				31276
Front bumper clip		set	necessary	50.00	50.00
Front number plate	with casing	1	bent	55.00	55.00



22 - 170896

Our reference:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

		Total costs fo	r parts	21164.64	20302.56
		Sub- Total	costs	0.00	0.00
Front fender rh/lh		*	*	0.00	0.00
Parts Repair					
		Sub-Total costs	for parts =	1000.00	1000.00
Rear number plate with ca	asing	1	bet _	55.00	55.00
Reverse camera		1	malfunction	550.00	550.00
Rear fender arch garnish o	clip rh/lh	2sets	necessary	60.00	60.00
Tail gate inner trim clip		set	necessary	40.00	40.00
Rear end panel sealant		1	necessary	40.00	40.00
Rear bumper clip		set	necessary	50.00	50.00
Tail gate windscreen seala	int	1	necessary	60.00	60.00
Bonnet insulation clip		set	necessary	40.00	40.00
Date 14,	/07/2022				

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170896

Date

14/07/2022

Page

3

Section B: Labour Cost Calculation

	Hourly ra	te Manhr. Req.		Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.		0 36	\$	1,620.00	
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-c	Sub-contract work.			
Apply rust proofing on the adjacent panels.	Sub-contract work.			100.00	
Remove / replace aircon condenser and refill aircon gas	\$ 45.0	0 3	\$	135.00	
Remove / refix radiator, top up coolant & conduct pressure test	\$ 45.0	0 2	\$	90.00	
Remove and refix rear windscreen (2 man-job)	\$ 45.0	0 3.5	\$	157.50	
Remove and refix upholstery and cushion seat to facilitate repair	\$ 45.0	0 2	\$	90.00	
Transfer tailgate mechanism	\$ 45.0	0 1.7	\$	76.50	
Conduct water leak test for rear portion associated repair works	\$ 45.0	0 1.5	\$	67.50	
Remove and replace rear exhaust system	\$ 45.0	0 2	\$	90.00	
Remove and replace rear reverse sensor	\$ 45.0	0 1.8	\$	81.00	
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.0	0 1.5	\$	67.50	
	Total	labour cost	\$	4,275.00	

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: **6385 1171**

Our reference:

22 - 170896

Date

14/07/2022

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$20,302.56	
Labour Cost Calculation (See section B)		\$4,275.00	
Total cost		\$24,577.56	
Lump Sum		64.04F.F4	
Further discount	20%	\$4,915.51	
Total Repair Cost		\$19,600.00	

We would recommend a sum of	\$19,600.00	and	12	working days for repair	
No further items will be approved w	vithout our expressed	l written agreem	ent. Any sign	ificant additional	
items will be subject to a supplement	ntary report.				

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators


IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants


IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

























































































































































































































































































































































































































































































































































































































































































































































































































































































































SS1Y226T000N / SME MOTOR PTE LTD ENTRY DATE & TIME: 29/06/2022 17:28 (SGT) SUBMITTED BY: Chia Pei Ying VERSION: 1 (29/06/2022 17:28 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/06/2022 17:28 (SGT) Reported by Both Date of Accident 28/06/2022 09:05 (SGT) Exact Location of Accident KJE, Singapore Additional Location Information BEFORE PIE CHANGI EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SLR4375E**

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner YONGSHENG E&C PTE LTD Company Reg No 201717299D **Email Address** jerryxu5858@gmail.com Mobile Phone No (Phone) +65-97585858 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Mazda Model Cx-3 Variant Exact purpose for which vehicle was being used at time of Employment accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 2000

INSURANCE COMPANY

Name of Insurance Company EQ Insurance Company Ltd Policy Number / Cover Note Number DMPPHQ21-005674

DRIVER

Name of Driver **XU YONGJIAN** Passport No/FIN G0767321W Date Of Birth 01/09/1988 Occupation Outdoor

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver	08/02/2018 4 YEARS AND 4 MONTHS Male (Phone) +65-98151666 - jerryxu5858@gmail.com BLK 108C CANBERRA WALK #11-23 - 753108 No Employee No
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Chain Collision Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given?	No 4 Yes No Yes 1 No No No No
If yes, against whom?	
I WAS STATIONARY WAITING AS THERE'S A JAM AHEAD. SU IMAPACT CAUSED MY CAR TO HIT ONTO THE FRONT CAR. ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera?	DDENLY, I FELT A HUGE IMAPCT FROM THE REAR AND THE Yes No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver	SME9251C Private car

Contact Number	<u>-</u>
Address	-
Address complement	-
Postcode	-
Insurance Company Name	=
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMT1091X
Vehicle Manufacturer	*
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	7
Vehicle Category	Private car
Name of Driver	_
Contact Number	<u>=</u>
Address	-
Address complement	-
Postcode	* -
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	VEHICLE C
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLT4378L
Vehicle Manufacturer	= 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Vehicle Model	
Vehicle Variant	
Vehicle Colour	9
Vehicle Category	Private car
Name of Driver	-
Contact Number	2
Address	
Address complement	
Postcode	-
Insurance Company Name	-
Nature Of Damage	2
Details of property damaged in accident	VEHICLE D
No. Of Passenger (Including Driver)	•

INJURED PERSONS DETAILS

INJURED 1

Name of the same	
Name of injured person	UNKNOWN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	22
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver:
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or witcholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my daims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Dr

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



			Stati	Stationary waiting		95	there	Ś	's jam ahed.		
			I felt a l		huge	huge impact		from	rur		
	dul	the	implict	cores	my	COX	to	hit	onto	the	
_	front	c co	۸,								
						-					
					-						

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Oriver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnol