

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle N : SHC7391P

Make : HYUNDAI

Model : IONIQ(G3)

Date: 21/06/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT DOOR LH			\$ 1,797.20 <i>Ry</i>
1	FRT DOOR OUTER MOULDING LH			\$ 110.10 <i>ant</i>
1	FRT FENDER ASSY LH			\$ 663.00 <i>Ry</i>
1	REAR DOOR LH			\$ 2,147.90 <i>Ry</i>
1	REAR DOOR OUTER MOULDING LH			\$ 125.30 <i>ant</i>
1	FRT FENDER EMBLEM LH			\$ 86.50 <i>all</i>
1	REAR BUMPER COVER			\$ 459.40 <i>Ry</i>
10	REAR BUMPER CLIPS			\$ 22.00 <i>x</i>
1	ROCKER PANEL OUTER GARNISH LH			\$ 290.00 <i>Ry</i>
	SUB TOTAL			\$ 5,701.40
	LESS 20%			\$ 1,140.28
	DISCOUNTED TOTAL			\$ 4,561.12
	PETROL ONLY STICKER			\$ 40.00 <i>Ry</i>
	FRT DOOR COMFORT LOGO LH			\$ 75.00 <i>ant</i>
	REAR DOOR COMFORT LOGO LH			\$ 80.00 <i>ant</i>
				\$ 195.00 Nett
	Labour Charge			
	PANEL BEATING			\$ 1,100.00 <i>525</i>
	SPRAY PAINTING CHARGE			\$ 1,100.00 <i>✓</i>
	TUFF KOTE			\$ 120.00 <i>x</i>
	TRANSFER OF DOOR			\$ 240.00 <i>x</i>
	TOTAL LABOUR			\$ 2,560.00
	ESTIMATE TOTAL			\$ 7,316.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphui 97495749
 WP 21/6/23 @ 12pm
 03 days
 L/S Resurvey after repair
 Tanphui @ LK Consultants

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Team: ARC Repair TP(CFSO)1		JOB CARD Sales Order: 5901061		JC NO305558286	
CUSTOMER		REGN NO.: SHC7391P		MILEAGE	
CITYCAB PTE LTD		MAKE: HYUNDAI		FUEL	
CUSTOMER NO. 7010070		MODEL IONIQ(G2)		E.....1/2.....F	
ADDRESS 383 SIN MING DRIVE		YR OF MANU. 01.08.2018		DATE/TIME IN 21.06.2023 09:30	
Singapore SINGAPORE 575717		CHASSIS CODE KMHC851CVJU103741		TARGET DATE	
(R) 65551188 (O)				COMPLETION DATE/TIME:	
(P)					
COUNT CARD NO.					

JOB DESCRIPTION

Accident Date: 20.06.2023
NATURE: 3P 20.06.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHC7391P YY

Vehicle No.: SHC7391P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard