

(08/11/13) wef

ASS. REC. BY: /

Taufik

REF:

INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SH 7733EYr Regn: 209, MayType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: toyota priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 385017

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STOKB3FH 403080089Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R5R: 195/65R5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westerlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 21/6/23Survey held at Confort Logon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

S + RS, SI

Photos

Others

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE**

Vehicle No.: SH7733E  
 Make : TOYOTA  
 Model : PRIUS G4  
 DOA : 21.06.2023

Date : 21.06.2023  
 Insurance: INCOME  
 MVA : CHIANG  
 Admin :

| Part No. | Parts Description / Labour               | Qty | Unit Price | Amount                               |
|----------|------------------------------------------|-----|------------|--------------------------------------|
| 1        | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE     |     |            | \$1,054.71 <i>over</i>               |
| 1        | REAR TRUNK LID LOGO (PRIUS)              |     |            | \$60.80 <i>we</i>                    |
| 1        | REAR TRUNK LID LOGO (HYBRID)             |     |            | \$52.40 <i>we</i>                    |
| 1        | REAR TRUNK LID LOGO (TOYOTA STAR)        |     |            | \$52.90 <i>X</i>                     |
| 1        | REAR TRUNK COVER                         |     |            | \$1,303.29 <i>bt</i>                 |
| 1        | REAR TRUNK LOCK                          |     |            | \$254.40 <i>X</i>                    |
| 1        | REAR KEY LOCK ANTENNA                    |     |            | \$312.00 <i>X</i>                    |
| 1        | REAR WINDSCREEN GLASS W/MOULDING         |     |            | \$1,884.32 <i>7</i>                  |
| 1        | REAR TRUNK LID GLASS W/MOULDING          |     |            | \$1,787.79 <i>2 photo</i>            |
| 1        | REAR BUMPER                              |     |            | \$503.04 <i>de</i>                   |
| 1        | REAR BUMPER UNDER COVER                  |     |            | \$654.96 <i>de</i>                   |
| 1        | REAR BUMPER REINFORCEMENT                |     |            | \$378.32 <i>bt</i>                   |
| 1        | REAR BUMPER SIDE RETAINER LH             |     | \$112.70   | \$112.70 <i>de</i>                   |
| 1        | REAR BUMPER UNDER COVER CENTRE           |     |            | \$252.00 <i>mis</i>                  |
| 1        | REAR BUMPER SIDE UNDER COVER /LH         |     |            | \$148.40 <i>7</i>                    |
| 1        | REAR END PANEL                           |     |            | \$738.96 <i>bt</i>                   |
| 1        | REAR END PANEL GARNISH                   |     |            | \$165.80 <i>de</i>                   |
| 1        | TAIL LAMP UPPER LH                       |     | \$557.90   | \$557.90 <i>car</i>                  |
| 1        | TAIL LAMP LOWER LH /RH                   |     | \$570.00   | <i>RHX</i> \$1,142.80 <i>LH over</i> |
| 10       | REAR BUMPER CLIPS                        |     |            | \$22.00 <i>we</i>                    |
|          | <b>SUB TOTAL</b>                         |     |            | \$11,439.49                          |
|          | <b>LESS 25%</b>                          |     |            | \$2,859.87                           |
|          | <b>DISCOUNTED TOTAL</b>                  |     |            | <b>\$8,579.62</b>                    |
| 1        | REAR TRUNK LID APPS STICKER              |     |            | <i>we</i> \$40.00                    |
| 2        | REAR TRUNK LID COMFORT & TEL NO. STICKER |     | \$30.00    | <i>we</i> \$60.00                    |
| 2        | REAR FENDER ADVERTISEMENT LH/RH          |     | \$100.00   | <i>we</i> \$200.00                   |
| 1        | REAR BUMPER MAT                          |     |            | <i>we</i> \$50.00                    |
| 1        | REAR BUMPER ADVERTISEMENT                |     |            | <i>we</i> \$50.00                    |
| 1        | REAR BUMPER REVERSE SENSOR               |     |            | <i>we</i> \$135.70                   |
|          |                                          |     |            | <b>\$512.13</b>                      |
|          | <b>Labour Charge</b>                     |     |            |                                      |
|          | Panel Beating                            |     |            | <i>700</i> \$1,200.00                |
|          | Spray Painting Charge                    |     |            | <i>750</i> \$800.00                  |
|          | Wiring Charge                            |     |            | <i>30</i> \$60.00                    |
|          | Remove/Refix windscreen and lower glass  |     |            | <i>✓</i> \$180.00                    |
|          | Tuff Kote                                |     |            | <i>30</i> \$90.00                    |
|          | Towing Fee                               |     |            | <i>X</i> \$60.00                     |

|                             |                       |  |  |                    |
|-----------------------------|-----------------------|--|--|--------------------|
| Remove/Refix Reverse Sensor |                       |  |  | \$60.00            |
|                             | <b>TOTAL LABOUR</b>   |  |  | <b>\$2,450.00</b>  |
|                             | <b>ESTIMATE TOTAL</b> |  |  | <b>\$11,541.75</b> |
|                             |                       |  |  |                    |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495449  
 'wp' 21/6/73 @ 5pm  
 C/S Ready after repair  
 Tanpin 01/07/2020  
 4 days

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 21.06.2023 14:35 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5901108


JC NO305558289

|                                                                                                                                                                                |                                           |                         |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|-------------------------|
| CUSTOMER<br>MS COMFORT TRANSPORTATION PTE LTD<br>CUSTOMER NO. 7010045<br>ADDRESS 383 SIN MING DRIVE<br>Singapore SINGAPORE 575717<br>(R) 65508755 (O)<br>(P)<br>COUNT CARD NO. | REGN NO:<br>SH 7733E                      | MILEAGE                 |
|                                                                                                                                                                                | MAKE:<br>TOYOTA                           | FUEL<br>E.....1/2.....F |
|                                                                                                                                                                                | MODEL<br>PRIUS HYBRID(G4)21.06.2023 12:50 | DATE/TIME IN            |
|                                                                                                                                                                                | YR OF MANU.<br>02.05.2019                 | TARGET DATE             |
|                                                                                                                                                                                | CHASSIS CODE<br>JTDKB3FU403080089         | COMPLETION DATE/TIME:   |
|                                                                                                                                                                                |                                           |                         |

### JOB DESCRIPTION

Accident Date: 21.06.2023  
 ATURE: 3P 21.06.2023

/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SH 7733E CHIANG

Vehicle No.: SH 7733E

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard