

(08/11 /13) wef

ASS. REC. BY: /

Taufikh

REF:

NS/INC23006320/Tnp3

INC.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. MT/1228453-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 7733EYr Regn: 209, MayType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: toyota priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 385017

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STOKB3FH 403080089Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westerlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 21/6/23Survey held at Conquest LogonDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Taufikh confirmed lump sum \$5650 and 4 days

(red. \$5891.75, 51%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SH7733E
 Make : TOYOTA
 Model : PRIUS G4
 DOA : 21.06.2023

Date : 21.06.2023
 Insurance: INCOME
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$1,054.71 <i>over</i>
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80 <i>we</i>
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40 <i>we</i>
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90 <i>X</i>
1	REAR TRUNK COVER			\$1,303.29 <i>bt</i>
1	REAR TRUNK LOCK			\$254.40 <i>X</i>
1	REAR KEY LOCK ANTENNA			\$312.00 <i>X</i>
1	REAR WINDSCREEN GLASS W/MOULDING			\$1,884.32 <i>7</i>
1	REAR TRUNK LID GLASS W/MOULDING			\$1,787.79 <i>2 photo</i>
1	REAR BUMPER			\$503.04 <i>de</i>
1	REAR BUMPER UNDER COVER			\$654.96 <i>de</i>
1	REAR BUMPER REINFORCEMENT			\$378.32 <i>bt</i>
1	REAR BUMPER SIDE RETAINER LH		\$112.70	\$112.70 <i>de</i>
1	REAR BUMPER UNDER COVER CENTRE			\$252.00 <i>mis</i>
1	REAR BUMPER SIDE UNDER COVER /LH			\$148.40 <i>7</i>
1	REAR END PANEL			\$738.96 <i>bt</i>
1	REAR END PANEL GARNISH			\$165.80 <i>de</i>
1	TAIL LAMP UPPER LH		\$557.90	\$557.90 <i>car</i>
1	TAIL LAMP LOWER LH /RH		\$570.00	\$1,142.80 <i>RHX LH over</i>
10	REAR BUMPER CLIPS			\$22.00 <i>we</i>
	SUB TOTAL			\$11,439.49
	LESS 25%			\$2,859.87
	DISCOUNTED TOTAL			\$8,579.62
1	REAR TRUNK LID APPS STICKER			<i>we</i> \$40.00
2	REAR TRUNK LID COMFORT & TEL NO. STICKER		\$30.00	<i>we</i> \$60.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00	<i>we</i> \$200.00
1	REAR BUMPER MAT			<i>we</i> \$50.00
1	REAR BUMPER ADVERTISEMENT			<i>we</i> \$50.00
1	REAR BUMPER REVERSE SENSOR			<i>we</i> \$135.70
				\$512.13
	Labour Charge			
	Panel Beating			<i>700</i> \$1,200.00
	Spray Painting Charge			<i>750</i> \$800.00
	Wiring Charge			<i>30</i> \$60.00
	Remove/Refix windscreen and lower glass			<i>✓</i> \$180.00
	Tuff Kote			<i>30</i> \$90.00
	Towing Fee			<i>X</i> \$60.00

Remove/Refix Reverse Sensor				\$60.00
	TOTAL LABOUR			\$2,450.00
	ESTIMATE TOTAL			\$11,541.75

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495449
 'wp' 21/6/73 @ 5pm
 C/S Ready after repair
 Tanpin C/Khantowin
 4 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 21.06.2023 14:35

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5901108

JC NO305558289


Customer Name: COMFORT TRANSPORTATION PTE LTD	REGN NO: SH 7733E	MILEAGE
Customer NO: 7010045	MAKE: TOYOTA	FUEL E.....1/2.....F
Address: 383 SIN MING DRIVE Singapore SINGAPORE 575717	MODEL: PRIUS HYBRID(G4)21.06.2023 12:50	DATE/TIME IN
(R) 65508755 (O)	YR OF MANU: 02.05.2019	TARGET DATE
(P)	CHASSIS CODE: JTDKB3FU403080089	COMPLETION DATE/TIME:
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 21.06.2023

Accident Time: 3P 21.06.2023

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SH 7733E

CHIANG

Vehicle No.:

SH 7733E

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard