



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23001348/Dvy3m4-1	
			Date: 27/06/2023	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YP 6938A	Veh. Inspected	SMK 1458U
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/026884	Excess (\$)	0.00
	Assign From	HUEY NI	Assign Date	21/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA WISH	c.c	1794
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTDER12WX03003120	Colour	WHITE
	Odometer	238419 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	ROTALLA	6 mm
	L/H Front Tyre	215/45 R17	ROTALLA	6 mm
	R/H Rear Tyre	215/45 R17	ROTALLA	6 mm
	L/H Rear Tyre	215/45 R17	ROTALLA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/01/2023	Inspection Date	08/02/2023
	Survey held at	AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	