

REPAIR ESTIMATE*

DATE 20.06.2023

INCOME
CHIANG/M'SIAN

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER			de \$481.10
1	FRONT BUMPER MOULDING CENTRE			cut \$368.50
1	FRONT BUMPER GRILLE LH			cut \$186.90
1	FRONT DAY RUNNING LIGHT LH			un \$642.50
1	FRONT BUMPER BRACKET LH			X \$41.40
1	HEADLAMP LH			cut \$2,110.30
1	HEADLAMP SUPPORT PANEL			un \$949.30
1	FRONT FENDER LH			bt \$588.80
1	FRONT FENDR SHIELD LH			un \$164.70
1	FRONT FENDR EMBLEM RH			new \$28.80
1	FRONT WHEEL CAP LH			cut \$346.40
10	FRONT BUMPER CLIPS		\$2.20	all \$22.00
	SUB TOTAL		4132.80	\$5,930.70
	20.00%			\$1,186.14
	DISCOUNTED TOTAL		3306.29	\$4,744.56
	Labour Charge			
	Panel Beating		940 350	\$700.00
	Spray Paint		500	\$600.00
	Reset Front Wheel Alignment			\$60.00
	Check lighting		4246.29 30	\$60.00
	TOTAL LABOUR		4246.29	\$1,420.00
	ESTIMATE TOTAL		4693.400 2 days	\$6,164.56
	Tanfik 97495749 up 21/6/73 @ 4pm 1/3 rising after repair tanfik C Khanoun -2 days			
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.