

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

22/06/2023 11:25

JOB-NO: 85008986

OWNER'S PARTICULARS

NAME: MR NANYANG PTE. LTD

CONTACT: 90610691

Page 1 of 2

ADDRESS: NA

90610691

NA@gmail.com

VEHICLE DETAILS

LICENSE NO: GBL7524Y

TRANS: MANUAL

CHASSIS: LC0CE4DB8M0090141

MAKE / MODEL: BYD / T3

ENGINE: 321028528

OWNER'S INSURER: INCOME INSURANCE LIMITED

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	2,000.00	0.00	2,000.00		Y	1500
2 SUNDRIES	1.00	50.00	0.00	50.00		Y	20
3 RUST PROOFING	1.00	100.00	0.00	100.00		Y	60
4 DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	100
5 R&R PARKING SENSOR SET	1.00	60.00	0.00	60.00		Y	40
6 R&R BACK DOOR GLASS	1.00	180.00	0.00	180.00		Y	120
7 R&R BACK DOOR COMPONENTS	1.00	150.00	0.00	150.00		Y	60
8 R&R FLOOR PEDAL COVER, CHROME BOARD, TRIM BOARD	1.00	200.00	0.00	200.00		Y	80
9 R&R NECESSARY ITEMS TO ENABLE REPAIR	1.00	150.00	0.00	150.00		Y	X
10 MOUNT WORKBENCH	1.00	400.00	0.00	400.00		Y	X
11 SPRAY PAINT FOR REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
12 SPRAY PAINT FOR BACK DOOR	1.00	350.00	0.00	350.00		Y	250
13 SPRAY PAINT FOR FLOOR PANEL	1.00	250.00	0.00	250.00		Y	200
14 SPRAY PAINT FOR REAR WALL PLATE	1.00	200.00	0.00	200.00		Y	150
15 SPRAY PAINT FOR SIDE BODY PANEL (REAR FENDER PORTION)	1.00	250.00	0.00	250.00		Y	200
16 SPRAY PAINT FOR ROOF TOP PANEL	1.00	250.00	0.00	250.00		Y	X
17 SPRAY PAINT FOR REAR WHEEL HOUSE PANEL RH	1.00	250.00	0.00	250.00		Y	X
TOTAL:		5,270.00	0.00	5,270.00			

MATERIALS

1 COMBINATION LAMP ASSY, RR <i>de</i>	1.00	362.97	0.00	362.97	L	Y	
2 SMALL REVERSING DETECTOR ASSY <i>de</i>	2.00	145.28	0.00	145.28	L	Y	
3 MOUNTING CLIP, DETECTOR <i>de</i>	2.00	5.32	0.00	5.32	L	Y	
4 VENT ASSY, LUGGAGE COMPARTMENT <i>X</i>	1.00	14.57	0.00	14.57	L	Y	
5 REAR BUMPER ASSY <i>de</i>	1.00	1,038.17	0.00	1,038.17	L	Y	
6 RUBBER BRACKET, REAR FOG LAMP, <i>new</i>	1.00	5.96	0.00	5.96	L	Y	
7 RUBBER BRACKET, REAR FOG LAMP, <i>new</i>	1.00	5.96	0.00	5.96	L	Y	
8 FRONT MOUNTING BRACKET ASSY, REAR BUMPER, R <i>new</i>	1.00	20.95	0.00	20.95	L	Y	
9 RIGHT MOUNTING BRACKET II ASSY, REAR BUMPER <i>new</i>	1.00	12.34	0.00	12.34	L	Y	
10 LIGHT GARNISH ASSY, REAR LICENSE PLATE <i>CPH</i>	1.00	320.75	0.00	320.75	L	Y	
11 "T3" MARK ASSY <i>new</i>	1.00	15.00	0.00	15.00	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
12 PEDAL, REAR RAIL <i>fix?</i>	1.00	26.80	0.00	26.80	L	Y	
13 INTERIOR SHIELD ASSY, BACK DOOR <i>sea</i>	1.00	194.09	0.00	194.09	L	Y	
14 BACK DOOR ASSEMBLY <i>buc</i>	1.00	13,285.11	0.00	13,285.11	L	Y	
15 SIDE BODY PANEL ASSY, R <i>repur</i>	1.00	12,035.97	0.00	12,035.97	L	Y	
16 REINFORCING PLATE, REAR WALL PLATE (REAR END PANEL OUTER) <i>bt</i>	1.00	734.34	0.00	734.34	L	Y	
17 REAR WALL PANEL ASSY (REAR END PANEL INNER) <i>bt</i>	1.00	2,650.31	0.00	2,650.31	L	Y	
18 PANEL COVER, FLOOR (CHROME BOARD) <i>bt</i>	1.00	3,413.25	0.00	3,413.25	L	Y	
19 WEATHERSTRIP, BACK DOOR FRAME <i>cul</i>	1.00	97.95	0.00	97.95	L	Y	
20 COMBINATION LAMP GUIDE CLIP SET RH <i>rh</i>	1.00	25.00	0.00	25.00 <i>15</i>	S	Y	
21 REAR BUMPER CLIP SET <i>m</i>	1.00	50.00	0.00	50.00 <i>30</i>	S	Y	
22 BACK DOOR GLASS SEALANT <i>m</i>	1.00	50.00	0.00	50.00 <i>40</i>	S	Y	
23 BACK DOOR GLASS PRIMER <i>m</i>	1.00	30.00	0.00	30.00 <i>20</i>	S	Y	
24 BACK DOOR STICKER (70 KM/H) <i>m</i>	1.00	20.00	0.00	20.00 <i>10</i>	S	Y	
25 BACK DOOR STICKER (6 PAX) <i>m</i>	1.00	20.00	0.00	20.00 <i>10</i>	S	Y	
26 SIDE BODY PANEL SEALANT RH <i>X</i>	1.00	50.00	0.00	50.00 <i>X</i>	S	Y	
27 REAR WALL PLATE SEALANT <i>m</i>	1.00	40.00	0.00	40.00	S	Y	
28 REPAIR REAR FLOOR PANEL <i>repur</i>	1.00	0.00	0.00	0.00	S	Y	
TOTAL:		34,670.09	0.00	34,670.09			
TOTAL PARTS & LABOUR :		39,940.09	0.00	39,940.09			

EXCESS/LOADING:\$ 0.00

No. Of Day: 10 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 22, 06, 23 @ 1540

SURVEYED BY: Rasul

CONTACT NO: 90010068

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STAAUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: