

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0586/2023/EQ
DATE : 21-Jun-23
WIP : 25626

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2023

YOUR INSURED VEH NO : SJW 8002 C

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

OWNER'S NAME : DR ZHENG ZHONGXI
ADDRESS : 141 TANAH MERAH KECHIL ROAD SOUTH
SINGAPORE 466672

TELEPHONE : HP +65 81280462
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700075696-05
VEHICLE NO : **SLT 7333 X**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 9/11/2017
ENGINE NO : CVN 041319
CHASSIS NO : WAUZZZF40HA182345
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jun-23
PLACE OF ACCIDENT : PIE TOWARDS CHANGI BEFORE EUNOS EXIT LANE 1.
REAR ENDED AFTER EMERGENCY BRAKE IN THE CARS
INFRONT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 7333 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00 700	
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	2,000.00 700	
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$	480.00	x
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	<u>4,432.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7333 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Del d</i>	1	\$	2,763.00	✓
2	REAR BUMPER FIXING PARTS <i>re m</i>	1	\$	496.00	+
3	REAR BUMPER SECURING STRIP ?	1	\$	264.00	?
4	REAR BUMPER SPOILER <i>re m</i>	1	\$	292.00	✓
5	REAR BUMPER REFLECTOR - LH / RH <i>re m</i>	2	\$	98.00	+
6	REAR BUMPER REINFORCEMENT BEAM <i>re m</i>	1	\$	1,197.00	+
7	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>re m</i>	2	\$	34.00	+
8	REAR BUMPER GUIDE SECTION - LH / RH UPPER <i>re m</i>	2	\$	106.00	+
9	REAR BUMPER GUIDE SECTION - LH / RH LOWER <i>re m</i>	2	\$	54.00	+
10	REAR PARKING AID SENSOR - INNER / OUTER <i>re m</i>	2	\$	543.00	+
11	REAR PARKING AID SEAL RING <i>re m</i>	4	\$	11.00	+
12	REAR SILENCER <i>re m</i>	1	\$	1,619.00	+
13	REAR SILENCER DUAL CLIP <i>re m</i>	1	\$	61.00	+
14	SUNDRIES ?		\$	500.00	?
TOTAL SPARE PARTS			:	\$	8,038.00
TOTAL LABOUR CHARGES			:	\$	4,432.00
GRAND TOTAL			:	\$	12,470.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Ly
28/06/23

Not Authorised, 03 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT