PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/TP/0586/2023/EQ

DATE : 21-Jun-23 **WIP** : 25626

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2023

YOUR INSURED VEH NO: SJW 8002 C

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

OWNER'S NAME : DR ZHENG ZHONGXI

ADDRESS : 141 TANAH MERAH KECHIL ROAD SOUTH

SINGAPORE 466672

 TELEPHONE
 : HP +65 81280462

 TYPE OF CLAIM
 : THIRD PARTY CLAIM

 POLICY NO
 : 1700075696-05

VEHICLE NO : SLT 7333 X

MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S

 MODEL YEAR
 : 9/11/2017

 ENGINE NO
 : CVN 041319

CHASSIS NO : WAUZZZF40HA182345

MILEAGE : DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 20-Jun-23

PLACE OF ACCIDENT: PIE TOWARDS CHANGI BEFORE EUNOS EXIT LANE 1.

REAR ENDED AFTER EMERGENCY BRAKE IN THE CARS

INFRONT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 7333 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
3/14	NATURE OF JOBS		CHARGES	RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,400.00	
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.		\$ 2,000.00	
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N	\$ 480.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 4,432.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7333 X

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,763.00	
2	REAR BUMPER FIXING PARTS	1	\$ 496.00	
3	REAR BUMPER SECURING STRIP	1	\$ 264.00	
4	REAR BUMPER SPOILER	1	\$ 292.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 98.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,197.00	
7	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	
8	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$ 106.00	
9	REAR BUMPER GUIDE SECTION - LH / RH LOWER	2	\$ 54.00	
10	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
11	REAR PARKING AID SEAL RING	4	\$ 11.00	
12	REAR SILENCER	1	\$ 1,619.00	
13	REAR SILENCER DUAL CLIP	1	\$ 61.00	
14	SUNDRIES		\$ 500.00	
	TOTAL SPARE PARTS	:	\$ 8,038.00	
	TOTAL LABOUR CHARGES	:	\$ 4,432.00	
	GRAND TOTAL	:	\$ 12,470.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO ALLAN WU

BODY REPAIR MANAGER CLAIMS CONSULTANT