

A.C.S. REG. BY:

REF:

CC4/AIS23006335/Dpa³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 34 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNE 8577H Yr Regn: April, 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer orMake: Mercedes Benz E550 C.C. 1991Colour: SILVER A/C: Insured / Std / NI / NASp. Reading: 109773 T/Radio: Insured / Std / NI / NAEng No: 27492030877867C.No: WDD2130452A*146684Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD ARim orTyre Size: F: 245/45 R18R: 11BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A. 19/06/2023 D.O.I. 23/06/2023Survey held at Alfred Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Allianz SMU 6519S</u>
<u>26/7/23</u>	<u>From 2/5 3,600/- with 4 days of rep</u>

Date/Time, File Pass to?



Prel. Report

Date/Time, File Return to?



Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inve (\$)

Survey Fee:

Transportation: S + RS \$

Photos

Others

Report Formals: _____

I certify that I am a member of the




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4382 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 200623

Date: 20.06.2023

Seow Siew Chern

Blk 11 Yishun Street 51 #08-23

Singapore 767971.

Mercedes Benz E250 AMG

Estimated Repair Cost for Vehicle Reg. No: SNE 8577 H


REPLACEMENT OF DAMAGED PANELS / PARTS

2 Pcs. Tail Lamp Assy. NH	@ 790.00	1,580.00 Nett. X
1 Pc. Rear Bumper Cnt		2,297.00 Nett. ✓
2 Pcs. Rear Bumper Retainer SN	@ 90.10	180.20 Nett. X
2 Pcs. Rear Bumper Top Holder broken	@ 199.80	399.60 Nett. ✓
1 Pc. Rear Bumper Centre Bracket broken		129.00 Nett. ✓
2 Pcs. Rear Bumper Side Bracket NH	@ 93.00	186.00 Nett. X
2 Pcs. Rear Bumper Reflector broken	@ 38.00	76.00 Nett. X
1 Pc. Rear Bumper Lower Chrome Moulding Cnt		350.00 Nett. ✓
1 Pc. Rear Bumper Lower Pad broken		305.00 Nett. ✓
1 Pc. Rear Bumper Towing Cover SN		95.00 Nett. X
2 Ps. Rear Bumper Exhaust Chrome broken	@ 448.00	896.00 Nett. X
10 Pcs. Rear Bumper Clips broken	@ 9.00	90.00 Nett. ✓ 30/- SN
8 Pcs. Rear Bumper Aluminum Rebit broken	@ 10.00	80.00 Nett. X ✓
6 Pcs. Rear Distance Sensor broken 4p 2pc Dm	@ 198.00	1,188.00 Nett. X ✓ 396.00
6 Pcs. Rear Sensor Spacer Ring broken	@ 12.00	72.00 Nett. X
1 Pc. Rear End Panel broken		1,679.00 Nett. X
1 Pc. Rear End Panel Garnish broken		180.00 Nett. X
4 Pcs. Rear End Panel Garnish Clips broken	@ 9.00	36.00 Nett. X
1 Pc. Rear Cross Member (Reinforcement) broken		989.00 Nett. X

Total (Panels / Parts): 10,621.80 (SGD)

3956.60
1070 3560.94

SN 30.00





ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To check lightings & wiring.	180.00 30/-
To use Xentry System to check control units, reset memory To standard settings.	480.00 180/-
To remove & refit interior garnish side board & all Accident affected area.	280.00 44
To knocking, straightening repair & renew all accident Affected area with refinish.	1,200.00 500/-
To respray painting on boot lid (inside & outside) lamp Panel, tail panel (inside & outside) bumper and all Accident affected area.	1,500.00 300/-
To rust proof all accident affected area.	120.00 44

1010.00

Total (Labor Charges): 3,760.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS
LABOR CHARGES

10,621.80
3,760.00

Grand Total: 14,381.80 (SGD)

Check part price

We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.