



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC23006337/Kqp3m4 Date: 27/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 376E	Veh. Inspected	SLX 1164K
	Policy No.		Coverage (\$)	0.00
	Claim No.	23/23/23/LL00/003840	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	03/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU IMPREZA (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JF1GT7KL5JG028388	Colour	M. P. WHITE
	Odometer	24528 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 ZR17	MICHELIN	9 mm
	L/H Front Tyre	205/50 ZR17	MICHELIN	9 mm
	R/H Rear Tyre	205/50 ZR17	MICHELIN	9 mm
	L/H Rear Tyre	205/50 ZR17	MICHELIN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/05/2023	Inspection Date	04/05/2023
	Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	