

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

PAGE 1 of 4

DATE: 21.06.2023

LKK-

MODEL: Hyundai i40

INSURANCE: CHINA TAIPING

4/5

VEHICLE NO: SHD3090D

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Bootlid	1		\$2,609.80	bt-
	Bootlid Rubber	1		\$96.50	bt-
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60	bt-
	Bootlid Lock Upper	1		\$114.90	bt-
	Bootlid Lock Lower	1		\$31.70	x
	Bootlid Key Lock	1		\$68.00	?
	Bootlid Hyundai Plate	1		\$21.10	na-
	Bootlid 'H' Emblem	1		\$63.10	na-
	Bootlid CRDI Plate	1		\$52.40	na-
	Bootlid Lamp (LH/RH)	2	\$622.60	\$1,245.20	cur-
	License Lamp (LH/RH)	2		\$56.10	x
	Bootlid Absorber	1		\$65.65	bt-
	Bootlid Trimboard	1		\$343.90	de-
	Bootlid Trimboard Clips (11 Pcs)	11	\$2.20	\$24.20	na-
	Bootlid I40 Emblem	1		\$67.90	na-
	Bootlid Lower Garnish	1		\$227.90	cur-
	Rear Bumper	1		\$1,106.00	ds-
	Rear Bumper Reinforcement Bracket	2	\$80.30	\$160.60	bt-
	Rear Bumper Reinforcement	1		\$428.40	cur-
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00	na-
	Rear Bumper Bracket RH / LH	2	\$35.60	\$71.20	ds-
	Rear Bumper Sponge	1		\$119.50	na-
	Rear Bumper Under Cover	1		\$228.00	na-
	Rear Bumper Reflector RH / LH	2	\$32.00	\$64.00	na-
	Tail Lamp (LH/RH)	2	\$697.80	\$1,395.60	cur-
	Tail Lamp Quarter Panel (LH/RH)	2	\$453.00	\$906.00	buc-
	Rear Panel	1		\$526.70	bt-
	Rear Panel Garnish	1		\$57.70	de-
	Rear Panel Lower Panel	1		\$495.50	bt-
	Spare Tyre Holder	1		\$248.00	?
	Tail Lamp Panel Top (LH/RH)	2	\$545.90	\$1,091.80	na- bu-
	Tail Lamp Lower Panel (LH/RH)	2	\$225.60	\$451.20	LHXR bu-
	Spare Wheel Lock Nut	1		\$41.80	?
	Spare Tyre Panel	1		\$852.80	?
	Spare Tyre Panel Cushion	1		\$223.10	?
	Rear Towing Hook	1		\$194.60	?
	Member-Assy-Rear Floor Centre	1		\$570.40	?
	Rear Panel Inner Panel RH	1		\$380.00	buc-
	Panel Assy-Rear Floor Side RH	1		\$180.20	buc-
	Extension Assy-Rear Floor RH	1		\$175.10	buc-

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			SHD3090H	PAGE 2 of 4
	Rear Chassis Member RH / LH	2	\$4,232.50	\$8,465.00 <i>LHXR RH?</i>
	Exhaust Pipe Insulator	1		\$117.10 <i>H-</i>
	Exhaust Silencer RH / LH	2	\$967.70	\$1,935.40 <i>LHX RHbt-</i>
	Exhaust Pipe Hanger	1		\$117.10 <i>?</i>
	Exhaust Pipe Centre	1		\$730.10 <i>?</i>
	Rear Fender 1/4 Glass RH	1		\$90.10 <i>cur-</i>
	Rear Fender RH / LH	2	\$2,171.40	\$4,343.40 <i>buc-</i>
	Rear Fender With Wheel Housing RH	1		\$4,736.80 <i>buc-</i>
	Rear Fender Inner Panel (LH/RH)	2	\$1,310.60	\$2,621.20 <i>LHX RHbuc-</i>
	Rear Fender Inner Lining (LH/RH)	2	\$169.30	\$338.60 <i>de-</i>
	Rear Fender Outer Corner Garnish (LH/RH)	2	\$33.60	\$67.20 <i>LH-? RHde-</i>
	Rear Fender Corner Hardboard Cover RH	1		\$213.25 <i>de-</i>
	Rear Tray Luggs Side (LH/RH)	2	\$232.60	\$465.20 <i>LH? RHde-</i>
	Rear Fender Air-Duct RH	1		\$51.60 <i>de-</i>
	Rear Fender Trim Board RH	1		\$688.75 <i>de-</i>
	Rear Windscreen Glass	1		\$607.20 <i>buc-</i>
	Rear Windscreen Moulding	1		\$51.80 <i>cur-</i>
	Rear Windscreen Inner Garnish	1		\$325.00 <i>de-</i>
	Speaker Panel	1		\$1,625.00 <i>buc-</i>
	Speaker Panel Air Duct	1		\$82.00 <i>?</i>
	Speaker Panel Cushion Cover	1		\$464.00 <i>de-</i>
	Third Brake Light	1		\$159.20 <i>?</i>
	Rear Door Black Plastic Cover RH	1		\$225.00 <i>dis-</i>
	Rear Door RH	1		\$2,416.80 <i>bt-</i>
	Rear Door Rubber RH	1		\$280.50 <i>cur-</i>
	Rear Door Glass RH	1		\$358.20 <i>cur-</i>
	Rear Door 1/4 Glass RH	1		\$284.70 <i>cur-</i>
	Rear Door Inner Moulding RH	1		\$152.40 <i>de-</i>
	Rear Door Outer Moulding RH	1		\$176.80 <i>de-</i>
	Rear Door Inner Handle RH	1		\$129.80 <i>cur-</i>
	Rear Door Outer Handle RH	1		\$134.50 <i>cur-</i>
	Rear Door Swith RH	1		\$112.00 <i>?</i>
	Rear Door Channel RH	1		\$73.55 <i>?</i>
	Rear Door Gear/Regulator RH	1		\$660.90 <i>?</i>
	Rear Door Power Motor RH	1		\$158.60 <i>?</i>
	Rear Door Module RH	1		\$242.80 <i>?</i>
	Rear Door Lock RH	1		\$468.20 <i>bt-</i>
	Rear Door 1/4 Glass Rubber RH	1		\$146.70 <i>cur-</i>
	Rear Door 1/4 Glass Pillar RH	1		\$164.40 <i>cur-</i>
	Rear Door Hinge Upper RH	1		\$114.50 <i>bt-</i>
	Rear Door Hinge Lower RH	1		\$123.50 <i>bt-</i>
	Rear Door Check RH	1		\$92.90 <i>bt-</i>
	Rear Door Trim Board RH	1		\$743.80 <i>de-</i>
	Rear Seat Upper Cushion	1		\$3,220.00 <i>?</i>
	Rear Seat Lower Cushion	1		\$2,990.00 <i>?</i>
	Rear Seat Upper Cushion Support Panel	1		\$2,950.00 <i>?</i>

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			SHD3090H	PAGE 3 of 4
	Rear Seat Lower Cushion Support Panel	1		\$2,850.00
	Door Centre Pillar Inner RH	1		\$1,224.20
	Door Pillar Enforcement RH	1		\$894.35
	Door Pillar Inner Garnish RH	1		\$326.40
	Fuel Lid Cover	1		\$82.10
	Fuel Lid Outer Garnish	1		\$59.40
	Rear Safety Belt Assy RH	1		\$477.20
	Rear Safety Belt Buckle RH	1		\$125.70
	Safety Belt Garnish Cover RH	1		\$171.70
	Rocker Panel Enforcement RH	1		\$1,163.30
	Rocker Panel Inner RH	1		\$1,285.50
	Rocker Panel Outer Garnish RH	1		\$732.80
	Rocker Inner Side Panel RH	1		\$175.90
	Rocker Panel Step Garnish (FRT) RH	1		\$31.70
	Rocker Panel Step Garnish (RR) RH	1		\$31.70
	Rear Tyre Rim RH	1		\$650.60
	Rear Tyre Wheel Cap RH	1		\$217.20
	Rear Wheel Bearing Ing & Hub RH	1		\$724.00
	Rear Trailing Arm RH	1		\$384.00
	Rear Assist RH	1		\$291.40
	Rear Shock Absorber RH	1		\$341.85
	Rear Shock Absorber Mounting RH	1		\$81.30
	Rear Cross Member	1		\$2,021.50
	Stabilizer Bar	1		\$399.20
	Stabilizer Link RH	1		\$85.90
	Rear Upper Arm RH	1		\$335.75
	Rear Lower Arm RH	1		\$353.80
	Rear Knuckle Arm RH	1		\$545.60
	Fire Extinguisher Holder	1		\$35.00
	SUB TOTAL			\$76,177.75
	LESS 20%			\$15,235.55
	DISCOUNTED TOTAL			\$60,942.20

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			SHD3090H	PAGE 4 of 4
	Rear Door Zig Apps RH	1		\$80.00
	BootLid ComfortDelgro	1		\$30.00
	BootLid 65521111	1		\$30.00
	BootLid Zig Apps	1		\$40.00
	Rear Bumper Mat	1		\$50.00
	Rear No.Plate With Trim Cover	1		\$55.00
	Reverse Sensors	1		\$135.70
	Rear Wheel Tyre RH	1		\$216.00
			80%	
	NETT TOTAL			\$636.70
	Labour Charge			
	Panel Beating			\$6,000.00
	Spray Painting Charge			\$2,000.00
	Wiring Charge			\$100.00
	Tuff Kote			\$200.00
	Towing Charge - King Dolly			\$150.00
	Rear Chassis Alignment Charge			\$400.00
	Remove/Refix Cushion & Upholstery Rear			\$150.00
	Remove/Refix Rear Windscreen Glass			\$120.00
	Remove/Refix Reverse Sensor			\$120.00
	Remove/Refix Undercarriage (RR)			\$400.00
	Remove/Refix Fuel Tank			\$150.00
	Remove/Refix Exhaust Pipe			\$150.00
	Four Wheel Alignment			\$120.00
	Diagnostic & Resetting To Erase Fault Code			\$480.00
	TOTAL LABOUR			\$ 10,540.00
	ESTIMATE TOTAL			\$ 72,118.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9749 5749
 WP 21/6/13 @ 430pm 20 days
 4/5 rising after repair
 - To provide taxi book value
 - To check repair limit
 Tanpin @ 1/11/13 auto.wm

Date/Time: 21.06.2023 14:00

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5901024

JC NO305558283

OMER	REGN NO: SHD3090D	MILEAGE
S COMFORT TRANSPORTATION PTE LTD 7010045	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. ESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	MODEL I-40	DATE/TIME IN 17.06.2023 06:15
	YR OF MANU. 16.06.2016	TARGET DATE
UNIT CARD NO.	CHASSIS CODE KMHLB41UMGU091454	COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 17.06.2023

ATURE: TP 17.06.2023 *Traffic POUND*

NO	LABOR CODE
0010	PB
0020	23-01

DESCRIPTION
PANEL BEATING-SHD3090D-TP
TOWING FEE-King Dolly



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Idgement Slip

Exit Pass

o.: SHD3090D LIMITS

Vehicle No.: SHD3090D

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

SHD 3090 D



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition	
1. Date: <u>19/8/25</u> Time Received: <u>9.45</u>	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/COPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Mr han.3</u> Contact No. : <u>98180451</u> Vehicle No. : <u>140</u> Make / Model / Colour : <u>SHD 3090 D</u> Email :	4. Type of Towing: <input type="checkbox"/> Normal Tow <input checked="" type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
5. Nature of Service: <input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>TP Company</u>	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:	10. Odometer Reading : _____ Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E
11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	 # : Cracked X : Dented / : Scratched O : Missing
Job Attended	
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input checked="" type="checkbox"/> GAO <input type="checkbox"/> OTHERS Name of Driver : <u>LKK</u> Vehicle No. : <u>n</u> Time Dispatch : <u>9.45</u> Time of Arrival : <u>4.00</u> Time Completed : <u>4.42</u>	
Signature of Customer _____	

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard