



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23006341/Knp3e2	
			Date: 04/07/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 6149P	Veh. Inspected	SHB 1872M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2302501/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTDKN36U705766963	Colour	METALLIC BROWN
	Odometer	794167 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	SAILUN	7 mm
	L/H Front Tyre	195/65 R15	SAILUN	7 mm
	R/H Rear Tyre	195/65 R15	SAILUN	6 mm
	L/H Rear Tyre	195/65 R15	SAILUN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/06/2023	Inspection Date	22/06/2023
	Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			