

ASS. REC. BY:

REF:

SMO/ 23 006341/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

861614

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMB 1872M

Yr Regn:

12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C

1798

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

794187

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36U705766963

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

195/65R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Daiun

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

21/6/23

D.O.I.

22/6/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s 2TH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

7/10/23

23/6

WCSy can find 7/10/23.

Purchase cost of Taxi = 898580.93 ÷ 96 mths = 9368.88

Balance mths = 6 × 9368.88 = 56161.28

28/6/23 submit uneconomical - \$8636.42

check: \$7869.69

Book value : \$6161

LTA

: \$5674

NV

: \$514

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

) S - RS. SI

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHB1872M
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6562727
Chassis No.:	JTDKN36U705766963
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	11 Dec 2015
First Registration Date:	11 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2023
PARF Rebate Amount:	\$3,000.00

Intended COE Rebate Details

COE Expiry Date:	10 Dec 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,466.00
COE Rebate Amount:	\$2,647.00
Total Rebate Amount:	\$5,647.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jun 2023

OK

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 22/06/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHB1872M
Case Reference Number	TAX/06/23/2060
Registration Date	11/12/15
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHIA YEW MENG
Type of Accident	Head to Rear
Accident Date and Time	21/6/23 3:15 PM
Accident Reported Date and Time	22/6/23 9:24 AM
Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118714
Special Instruction to ARC, if any	TP/ FRONT /REAR PORTION/ TOWED
Prepared Date and Time	22/6/23 9:33 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,366.00	\$0.00
Total Spray Cost	\$3,650.00	\$0.00
Total Spare Part Cost	\$20,696.06	\$0.00
Total Other Cost	\$2,206.00	\$0.00
TOTAL COST	\$28,918.06	\$0.00
Jump Sum Total	\$28,900.00	\$0.00
Number of Repair Days	12.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	22/06/2023 10:35 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
116055

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 22/06/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR FRONT PORTION	\$1,014.00 <i>800 400</i>	
O REPAIR REAR PORTION	\$1,352.00 <i>800</i>	
total Labour	\$2,366.00	

Part 2 - Spray Painting & Panel Beating Related Works


Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT BUMPER	\$378.00 <i>200</i>	
O RESPRAY FRONT HOOD	\$378.00 <i>200</i>	
O RESPRAY FRONT BUMPER LOWER GRILLE	\$220.00 <i>X</i>	
O RESPRAY FRONT SUPPORT PANEL	\$220.00 <i>?</i>	
O RESPRAY REAR BUMPER	\$378.00 <i>200</i>	
O RESPRAY BUMPER BEAM	\$220.00 <i>120</i>	
O RESPRAY REAR PANEL	\$220.00 <i>200</i>	
O RESPRAY TAIL GATE	\$378.00 <i>200</i>	
O RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00 <i>120</i>	
O RESPRAY REAR SPOILER	\$220.00 <i>X</i>	
O RESPRAY REAR SPARE TYRE PANEL	\$220.00 <i>?</i>	
O RESPRAY FLOOR CORNER PANEL RH	\$220.00 <i>?</i>	
O RESPRAY REAR FENDER RH	\$378.00 <i>200</i>	
total Spray Painting & Panel Beating	\$3,650.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	\$58.00 <i>✓</i>	
O WASH AND VACUUM	\$60.00 <i>X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>40</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00 <i>90</i>	
O TOP UP A/C GAS	\$120.00 <i>?</i>	
O CONDUCT RADIATOR PRESSURE CHECK	\$120.00 <i>?</i>	
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$600.00 <i>X</i>	
O TRANSFER REAR TAILGATE MECHANISM	\$120.00 <i>60</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>30</i>	
O REMOVE AND REFIX REAR WINDSCREEN	\$370.00 <i>120</i>	
O REPLACE SUNDRY PARTS	\$200.00 <i>X</i>	
O REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00 <i>30</i>	
total Other Costs	\$2,206.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>Mc ✓ ✓</i>
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$86.20	25.00	\$64.65	Replace	<i>Di ✓ ✓</i>
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$97.60	25.00	\$73.20	Replace	<i>?</i>
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$567.90	25.00	\$425.92	Replace	<i>R X</i>
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$284.00	25.00	\$213.00	Replace	<i>X X</i>
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	1.00	\$284.00	25.00	\$213.00	Replace	<i>R X</i>



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 22/06/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		56117-50140	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1.00	\$31.30	25.00	\$23.48	Replace <i>mu</i>	<i>—</i> ✓
		76085-47910	SPOILER REAR	1.00	\$1,263.70	25.00	\$947.78	Replace <i>mu</i>	<i>X</i>
		61601-47090	FENDER RR/RH	1.00	\$980.80	25.00	\$735.60	Replace <i>mu</i>	<i>—</i> ✓
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace <i>mu</i>	<i>—</i> ✓
			STICKER DECAL 85558888	1.00	\$21.60	0.00	\$21.60	Replace <i>mu</i>	<i>—</i> ✓
		62710-47130	QUARTER GLASS RR/RH	1.00	\$556.70	25.00	\$417.53	Replace	<i>?</i>
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace <i>mu</i>	<i>—</i> ✓
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace <i>mu</i>	<i>—</i> ✓
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$86.20	25.00	\$64.65	Replace <i>mu</i>	<i>X</i>
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace <i>3 part</i>	<i>—</i> ✓
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	<i>—</i> ✓
		81170-47500	HEAD LAMP LH	1.00	\$1,075.40	10.00	\$967.86	Replace	<i>?</i>
		68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$22.30	25.00	\$16.73	Replace <i>mu</i>	<i>—</i> ✓
		61621-47030	TROUGH, BACK DOOR	1.00	\$126.80	25.00	\$95.10	Replace	<i>?</i>
			SEALANT W/SCREEN (3PCS)	3.00	\$37.00	0.00	\$111.00	Replace <i>mu</i>	<i>—</i> ✓
		68810-47010	TAILGATE DOOR HINGE LH/RH (2 PCS)	2.00	\$61.20	25.00	\$91.80	Replace <i>mu</i>	<i>X</i>
		67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$402.50	25.00	\$301.88	Replace <i>mu</i>	<i>X</i>
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$574.80	25.00	\$431.10	Replace <i>mu</i>	<i>—</i> ✓
		75310-47020	EMBLEM REAR	1.00	\$68.70	25.00	\$51.53	Replace <i>mu</i>	<i>—</i> ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$59.20	25.00	\$44.40	Replace <i>mu</i>	<i>—</i> ✓
		75442-47030	NAME PLATE (PRUIS)	1.00	\$69.40	25.00	\$52.05	Replace <i>mu</i>	<i>—</i> ✓
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$59.20	25.00	\$44.40	Replace <i>mu</i>	<i>—</i> ✓
		65637-47021	FENDER LINE RR/RH	1.00	\$159.80	25.00	\$119.85	Replace <i>mu</i>	<i>X</i>
		52562-47010	TAIL LAMP BRACKET, RH	1.00	\$35.20	25.00	\$26.40	Replace <i>mu</i>	<i>—</i> ✓
		81551-47180	TAIL LAMP RH	1.00	\$618.60	10.00	\$556.74	Replace <i>CRA</i>	<i>—</i> ✓
		53113-47040	GRILLE, RADIATOR LOWER NO.2	1.00	\$118.30	25.00	\$88.73	Replace	<i>?</i>
		78851-47020	BUMPER LIP FRT	1.00	\$182.70	25.00	\$137.02	Replace <i>mu</i>	<i>X</i>
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$159.30	25.00	\$119.48	Replace <i>mu</i>	<i>X</i>
		53301-47060	HOOD PANEL	1.00	\$988.50	25.00	\$741.38	Replace <i>mu</i>	<i>—</i> ✓
		53341-47020	HOOD PANEL INSULATOR	1.00	\$445.00	25.00	\$333.75	Replace <i>mu</i>	<i>X</i>
		53420-47070	HOOD HINRE LH	1.00	\$63.70	25.00	\$47.78	Replace <i>mu</i>	<i>X</i>
		53410-47070	HOOD HINGE RH	1.00	\$63.70	25.00	\$47.78	Replace <i>mu</i>	<i>X</i>
		53510-47102	HOOD LOCK	1.00	\$146.10	25.00	\$109.57	Replace <i>mu</i>	<i>X</i>
		58307-47060	END PANEL	1.00	\$755.10	25.00	\$566.33	Replace <i>mu</i>	<i>X</i>
		58311-47071	SPARE TYRE PANEL	1.00	\$755.10	25.00	\$566.33	Replace <i>mu</i>	<i>X</i>
		67005-47241	TAILGATE ASY	1.00	\$1,260.70	25.00	\$945.53	Replace <i>mu</i>	<i>—</i> ✓
		75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$33.60	25.00	\$25.20	Replace <i>mu</i>	<i>—</i> ✓
		75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$33.60	25.00	\$25.20	Replace <i>mu</i>	<i>—</i> ✓
		68105-47122	TAILGATE DOOR GLASS	1.00	\$1,273.10	25.00	\$954.82	Replace <i>mu</i>	<i>X</i>
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$33.60	25.00	\$25.20	Replace <i>mu</i>	<i>—</i> ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 22/06/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53293-47040	DEFLECTOR, RADIATOR RH	1.00	\$94.30	25.00	\$70.73	Replace	Sh X
		53294-47030	DEFLECTOR, RADIATOR LH	1.00	\$86.90	25.00	\$65.18	Replace	Sh X
		52114-47140	BRACKET, FR BUMPER	1.00	\$126.10	25.00	\$94.57	Replace	R X
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$21.40	25.00	\$16.05	Replace	Sh X
		52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$21.40	25.00	\$16.05	Replace	Sh X
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$389.90	25.00	\$292.42	Replace	?
		75310-47010	EMBLEM FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Sh ✓
		53395-47020	HOOD END PANEL SEAL	1.00	\$80.60	25.00	\$60.45	Replace	R X
		53289-47032	COVER, RADIATOR	1.00	\$139.30	25.00	\$104.48	Replace	?
		53111-47040	GRILLE, RADIATOR	1.00	\$389.30	25.00	\$291.98	Replace	?
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,839.70	25.00	\$1,379.78	Replace	R X
		81130-47500	HEAD LAMP RH	1.00	\$1,075.40	10.00	\$967.86	Replace	?
		88460-47150	A/C CONDENSER	1.00	\$1,695.90	25.00	\$1,271.93	Replace	?
		16400-37230	RADIATOR ASSY	1.00	\$2,245.70	25.00	\$1,684.27	Replace	?
		16534-37010	SUPPORT RADIATOR, LH	1.00	\$23.40	25.00	\$17.55	Replace	?
		16533-28051	SUPPORT RADIATOR, RH	1.00	\$72.00	25.00	\$54.00	Replace	?
		16535-20030	SUPPORT, RADIATOR (2 PCS)	2.00	\$24.80	25.00	\$37.20	Replace	?
			COOLANT (ADD QTY)	4.00	\$12.32	0.00	\$49.28	Replace	?
		16711-37040	FAN SHROUD	1.00	\$321.40	25.00	\$241.05	Replace	Sh X
		16712-37030	FAN SHROUD TOP	1.00	\$131.50	25.00	\$98.63	Replace	Sh X
		16361-37010	FAN BLADE	1.00	\$236.90	25.00	\$177.68	Replace	Sh X
		16361-28360	FAN BLADE NO.2	1.00	\$305.50	25.00	\$229.13	Replace	Sh X
		16363-37010	FAN MOTOR NO.1	1.00	\$708.40	10.00	\$637.56	Replace	Sh X
		16363-37020	FAN MOTOR NO.2	1.00	\$708.40	10.00	\$637.56	Replace	Sh X
		8837047092	AIR CON COMPRESSOR ASSY	1.00	\$5,160.70	25.00	\$3,870.52	Replace	Sh X
		52159-47905	BUMPER REAR	1.00	\$478.90	25.00	\$359.17	Replace	CRS ✓
		90467-07211	BUMPER CLIPS (10 PCS)	10.00	\$2.40	25.00	\$18.00	Replace	Sh ✓
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$234.70	25.00	\$176.02	Replace	Sh ✓
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	1.00	\$157.90	25.00	\$118.43	Replace	?
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$157.90	25.00	\$118.43	Replace	?
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$208.10	10.00	\$187.29	Replace	?
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Per ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$108.70	25.00	\$81.53	Replace	Dir ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$108.70	25.00	\$81.53	Replace	CRS ✓
		52592-47021	BUMPER SEAL, RR LH	1.00	\$101.80	25.00	\$76.35	Replace	?
		52591-47021	BUMPER SEAL, RR RH	1.00	\$74.40	25.00	\$55.80	Replace	?
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$93.90	25.00	\$70.43	Replace	XNN
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$155.40	25.00	\$116.55	Replace	XNN
		76891-47020	BUMPER LIP REAR	1.00	\$301.90	25.00	\$226.42	Replace	Sh X
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Sh X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/06/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$33.60	25.00	\$25.20	Replace <i>mu</i>	<i>—</i> ✓
		64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$827.50	25.00	\$620.63	Replace <i>sm</i>	<i>X</i>
total					\$33,927.12		\$26,426.82		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									