K	MARTA	300.6344/kg
, , ,	ASS	IGNMENT
	From: Dale:	Veh No: SK & 4444U Yr Regn: 06, 2.
	Estimated Cost:	Type: MCarl M Code / Bus Was Hard Transfer Co
	OD LATE I WS / TP RES / OD RES / EVA / INV / MV	Type: McCar / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or
	To Inspect Vehicle No:	$ \mathcal{A}$)
	at Workshop m/s	10511 MODEL / CC -
	of Optime	Colour M.P. White AC: Insured / Std / HI / NA
	Insured:	- V - L
	Policy No.	Eng/No:
	Claims No.	CNO: HELRWYHCE-SAPEP9.
		Gen. Cond: Good / Fair / Poor / Burnt
	(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
	(Chen's Record) Make of Veh:	Brake: Inorder/ Jammed / Leaked / Burnt or
		Modi: NII / S/Rim / STD MORITA or
	10 am	Tyre Stze: F: 255/45 R 19
	(Policy Condition)	R:
	Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	repair at the time of inspection.	TOYO/YOKO or
	Bal. or Market Value:	Front Rear
	IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm · R/Rel Q
	GIA / PR Seen: Consistent?: Yes or No	L/Bail. 9 mm L/Bail. 9
i:	Est Repairs: 05 days Res.: Yes or No	10///a
ř.	um Com / / / / 2 Val. Van - 1	5.0.1. 1976/23 D.O.I. 27/6/20
	♣ -	
	Vehicle: IN / OUT	Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
į	Date:Person Contacted:	a co
_	Date / Time Action / Instruction	The U/C / Chasals frame / Body Structure affected due to collision.
		designation of the second seco
13		
!		
		The state of the s
	Charles	
	Cata/Time, File Pass to? Preli. Report Day	ys Of Repair:
	: Final Report	
	Outs/Time, File Return to?	
	Add Fee:	Transportation (\$
	אמט רשש:	: Site Insp (\$) _ s - RS _ SI
		lade at the state of the state
	Report Format	: Interview (\$) Firsts
	Report Format :	: Interview (\$) Find 35 Tech Invs (\$) Others

OPT/MA///ERKZ

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sq

(7) /OptimaWerkz

/OptimaWerkz

Date:

21/06/2023

Not Nothering Recommy B4 paint RWD 1277-2023 Sday

SINGAPORE

Third Party Insurer:

EQ INSURANCE

Vehicle No: SKE4444U Model:

TESIA MODEL Y RWD

Third Party Veh No: Date of Accident:

GBF8827Z

Chassis:

LRWYHCFS9PC891577-2023

19/06/2023

Reg.Year:

2023

Estimator:

TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER RH	1		B \$1,551.40
1		1		Ma \$121.50
2	REAR FENDER QUARTER GLASS RH	1		\$65.42
3	REAR FENDER WHEEL ARCH RH	1		CM \$836.45
4	REAR BUMPER	1		\$5.61
5	REAR BUMPER SIDE BRACKET RH	1		\$5.01
				\$2,580.38
		SUB TOTAL		
			LESS 10%	-\$258.04
			PARTS TOTAL	\$2,322.34

SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
	1		Ma \$80.00	
	1		N \$40.00	
	1		Ma \$50.00	
CERAMIC COATING FOR AFFECTED AREAS	1		\$1,000.00	
		S/NI TOTAL	\$1,170.00	
	REAR FENDER QUARTER GLASS SEALANT RH REAR FENDER WHEEL ARCH CLIPS RH REAR BUMPER CLIPS	REAR FENDER QUARTER GLASS SEALANT RH REAR FENDER WHEEL ARCH CLIPS RH REAR BUMPER CLIPS 1 CERAMIC COATING FOR AFFECTED AREAS 1	REAR FENDER QUARTER GLASS SEALANT RH 1 REAR FENDER WHEEL ARCH CLIPS RH 1 REAR BUMPER CLIPS 1	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER RH, REAR BUMPER & ETC.

\$600.00 4801

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS, REAR FENDER QUARTER GLASS SEALANT & ETC.

\$150.00 6

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$400.00 100/

6 Kung Chong Road Singapore 159143 Tel: (-66) 6472 1313 | Fax: (-66) 6472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+85) 6484 9919 | Fax: (+65) 6481 1993

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 588047
Tel. (-65) 6481 1522 | Fax: (-65) 4491 5015 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sq

(7) /OptimaWerkz

/OptimaWerkz

Date:

21/06/2023 Vehicle No: SKE4444U

Model:

TESLA MODEL Y RWD

Chassis:

LRWYHCFS9PC891577-2023

Reg.Year:

2023

Third Party Insurer:

EQ INSURANCE

Third Party Veh No: Date of Accident:

GBF8827Z

Estimator:

19/06/2023 **TING AN**

Surveyor:

\$150.00 30/

\$120.00 20/

TO TUFF KOTE & UNDERSEAL MATERIALS.

TO CHECK WIRING & ELECTRICAL SYSTEM.

LABOUR TOTAL

\$2,120.00

TING AN

TOTAL

\$5,612.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witnoiding or material racts may allow miscurate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/06/2023 18:19 (SGT) Reported by **Actual Driver Date of Accident** 19/06/2023 16:36 (SGT) **Exact Location of Accident** 782E Woodlands Cres, Singapore 735782 Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKE4444U

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner JULIYATI BT ABDULLAH NRIC No SXXXX361D **Email Address** juliyatia@gmail.com Mobile Phone No (Phone) +65-91805393 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Tesla Model MODEL Y RWD Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to Private use your vehicle? Vehicle Category No - Claiming third party Transmission Private car CC Auto

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

Liberty Insurance Pte Ltd SD23V07762 /VPS /R00

1999


DRIVER

Name of Driver NRIC No Date Of Birth Occupation

MUHAMMAD SOFIAN BIN MOHD SHARIFF SXXXX355F 01/10/1984 Outdoor

Accident report SO03236K0005

SKETCH PLAN



A= SKE 44440 B=GBF88272

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Recer to	Police	Perert	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1 2 2 2			5x + 5
,			- 2
Y			
		The state of the s	
	-		\dashv
			_
			\dashv

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Sang JU M NRIC/FIN No.: 5 6 5 W