

ASS. REC. BY:

REF:

EQ / 23006344 / K9P3

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SK E 4444U Yr Regn: 06, 23Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Tesla Model X C.C. \_\_\_\_\_Colour M.P. White A/C: Insured / Std / NI / NASp. Reading 852 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: LR WYHCF59PC 891571Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / Rim orTyre Size: F: 255/45 R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 19/6/23D.O.A. 27/6/2023

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop oro/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/7 @ 3703.46 Carhit (Red # 1908.88, 347)

Date/Time, File Pass to?

☐

: Prel. Report

1) 19/7 1908.88

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS. \$

) Fuel

) Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / I.B.I.: (\$)

TP

3703.46

TOTAL

Date: 21/06/2023

Vehicle No: SKE4444U

Model: TESLA MODEL Y RWD

Chassis: LRWYHCF59PC891577-2023

Reg. Year: 2023

*Not Notified*  
*Runny B & paint*

*5 days*

*\$ 3703.46*

Third Party Insurer: EQ INSURANCE

Third Party Veh No: GBF8827Z

Date of Accident: 19/06/2023

Estimator: TING AN

Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                  | QTY | UNIT S\$ | AMOUNT S\$           |
|-------------|------------------------------|-----|----------|----------------------|
| 1           | REAR FENDER RH               | 1   |          | <i>RM</i> \$1,551.40 |
| 2           | REAR FENDER QUARTER GLASS RH | 1   |          | <i>RM</i> \$121.50   |
| 3           | REAR FENDER WHEEL ARCH RH    | 1   |          | <i>RM</i> \$65.42    |
| 4           | REAR BUMPER                  | 1   |          | <i>CM</i> \$836.45   |
| 5           | REAR BUMPER SIDE BRACKET RH  | 1   |          | <i>CM</i> \$5.61     |
| SUB TOTAL   |                              |     |          | \$2,580.38           |
| LESS 10%    |                              |     |          | -\$258.04            |
| PARTS TOTAL |                              |     |          | \$2,322.34           |

| NO.       | SPECIAL NETT                         | QTY | UNIT S\$ | AMOUNT S\$           |
|-----------|--------------------------------------|-----|----------|----------------------|
| 1         | REAR FENDER QUARTER GLASS SEALANT RH | 1   |          | <i>RM</i> \$80.00    |
| 2         | REAR FENDER WHEEL ARCH CLIPS RH      | 1   |          | <i>RM</i> \$40.00    |
| 3         | REAR BUMPER CLIPS                    | 1   |          | <i>RM</i> \$50.00    |
| 4         | CERAMIC COATING FOR AFFECTED AREAS   | 1   |          | <i>RM</i> \$1,000.00 |
| S/N TOTAL |                                      |     |          | \$1,170.00           |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

*600*  
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER RH, REAR BUMPER & ETC.

*440*  
\$600.00

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS, REAR FENDER QUARTER GLASS SEALANT & ETC.

*60*  
\$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

*100*  
\$400.00

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 21/06/2023  
 Vehicle No: SKE4444U  
 Model: TESLA MODEL Y RWD  
 Chassis: LRWYHCF59PC891577-2023  
 Reg. Year: 2023

Third Party Insurer: EQ INSURANCE  
 Third Party Veh No: GBF8827Z  
 Date of Accident: 19/06/2023  
 Estimator: TING AN  
 Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 3cl

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 2cl

LABOUR TOTAL \$2,120.00

TING AN

TOTAL \$5,612.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Head office**

6 Kung Cheng Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                |
|-------------------------------------|--------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                |
| Owner ID Type:                      | Singapore NRIC                 |
| Owner ID:                           | 361D                           |
| <b>Vehicle Details</b>              |                                |
| Vehicle No.:                        | SKE4444U                       |
| Vehicle to be Exported:             | No                             |
| Intended Deregistration Date:       | 13 Sep 2023                    |
| Vehicle Make:                       | TESLA                          |
| Vehicle Model:                      | MODEL Y RWD                    |
| Primary Colour:                     | White                          |
| Manufacturing Year:                 | 2023                           |
| Engine No.:                         | -                              |
| Chassis No.:                        | LRWYHCFS9PC891577              |
| Maximum Power Output:               | 220.0 kW (295 bhp)             |
| Open Market Value:                  | \$60,290.00                    |
| Original Registration Date:         | 12 Jun 2023                    |
| First Registration Date:            | 12 Jun 2023                    |
| Transfer Count:                     | 0                              |
| Actual ARF Paid:                    | \$41,725.00                    |
| <b>Intended PARF Rebate Details</b> |                                |
| PARF Eligibility:                   | Yes                            |
| PARF Eligibility Expiry Date:       | 11 Jun 2033                    |
| PARF Rebate Amount:                 | \$31,293.00                    |
| <b>Intended COE Rebate Details</b>  |                                |
| COE Expiry Date:                    | 11 Jun 2033                    |
| COE Category:                       | B - Car-Details at OneMotoring |
| COE Period(Years):                  | 10                             |
| QP Paid:                            | \$120,702.00                   |
| COE Rebate Amount:                  | \$117,631.00                   |
| <b>Total Rebate Amount:</b>         | <b>\$148,924.00</b>            |

The information contained herein is correct as at 21 Jun 2023

OK