

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 04 Jul 2023

Preliminary Advice

Insured Vehicle No	: YP9222L		
TP Vehicle No	: SLS8392Z	Accident Date	: 20/06/2023
Make	: TOYOTA C-HR HYBRID	Assignment Date	: 22/06/2023
Date of Inspection	: 03/07/2023	Est. Duration of Repair	: 6
Inspection At	: LIAN HER MOTOR WORKS (HQ) BLOCK 5034 ANG MO KIO AVENUE 3, #01-337 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569537		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,269.58
Revised Amount	:S\$	5,573.03
Check Items (Estimated)	:S\$	629.70
Total	:S\$	6,202.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	23,959.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,041.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.