

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

H L Car Rental Pte Ltd  
Blk 5038 #01-405  
Ang Mo Kio Industrial Pk 2  
Singapore 569541

Vehicle No : SLS 8392 Z  
Make : Toyota C-HR  
Year : 2017

NOT AUTHORIZED

Permy After Paint

6 days

11 Day @ 5000/-

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear n/s door	B1	\$1,487.60	✓
1 pc	Rear n/s door outer protector	SL	\$405.10	X
1 pc	Rear n/s door rubber	Ln	\$185.60	X
1 pc	Rear n/s door regulator	n	\$235.10	X
1 pc	Rear n/s door regulator motor	n	\$425.60	X
1 pc	Rear n/s door frame black sticker	Ln	\$85.10	✓
1 pc	Rear n/s fender	B1	\$755.20	✓
1 pc	Rear n/s fender arch garnish	B1	\$185.70	✓
1 pc	Rear n/s fender innershield	CM	\$155.60	✓
1 pc	Fuel tank outer door cover	n	\$115.80	X
1 pc	Rear n/s tail-lamp	Ln	\$550.80	✓
1 pc	Rear top bumper	Ln	\$755.60	✓
1 pc	Rear lower bumper	Ln	\$485.60	✓
1 pc	Rear n/s bumper side retainer	Ln	\$85.10	✓
1 pc	Rear n/s shock absorber	Ln	\$425.60	X
1 pc	Rear n/s lower arm	Ln	\$497.20	X
1 pc	Rear n/s trailing arm	Ln	\$287.60	X
1 pc	Rear n/s knuckle arm	Ln	\$558.20	X
1 pc	Rear n/s hub	B1	\$496.50	✓
1 pc	Rear n/s hub bearing	Ln	\$187.50	✓
			\$8,366.10	
			Less 25 %	
			\$2,091.52	
			\$6,274.58	

## S Nett

1 pc	Rear n/s fender glass sealant
1 pc	Sundries
1 pc	Rear n/s tyre rim
1 pc	Rear n/s door edge lining

nn	\$30.00	X
nn	\$50.00	X
nn	\$450.00	✓
nn	\$100.00	30%
\$1,475.00		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

balance c/f \$6,904.58

Acknowledged by Repairer

Signature:

Date:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)

Report Format :

8392 Z

balance b/f \$6,904.58

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,600.00

9001

To putty & spray paint on accident affected portion.

\$1,600.00

8001

check/reconnect wiring.

\$45.00

201

to spray anti rust on accident affected portion.

\$180.00

601

remove/refit rear n/s door mechanism, glass to new door

\$120.00

601

remove/renew rear n/s undercarriages

nn

\$480.00 X

check and realign wheel alignment

\$80.00

601

remove/refit rear n/s fender glass to facilitate repair

nn

\$80.00 X

remove/refit roof lining to facilitate repair

\$180.00

1001

Total

\$11,269.58

Add Fee: ☐ : Site Insp (\$  
☐ : Interview (\$