

Reg No. : 196700086Z  
 T Reg No. : MR-8500000-9  
 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no: 6631 1188

## ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	M/S Lumens Pte. Ltd	
		Document No. 0	22 Sin Ming Lane #01-74 Midview City Singapore 573969	
		Document Date 23/06/2023	Mobile: 83221830	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ZWR80	CAT B	12/03/2020	SMS7502T	0	22678	72/DS/SMS7502T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
ZWR800432870		2ZR0F24798	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:INDIA INTERNATIONAL TP VEH:SLP6692L DATE OF ACC:19.06.2023 TOW IN:21.06.2023				50 <del>100.00</del>
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
3	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR				198.00
4	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				792 <del>1584.00</del>
5	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				656 <del>1988.00</del>
6	1	T53112-28310 GRILLE, RADIATOR, <del>Coat</del> X				
7	2	T53101-28670 C0 GRILLE SUB-ASSY, <del>Coat</del>	1.00	217.50		217.50
8	3	T52611-28111 ABSORBER, FR BUMPER X	1.00	1321.30		1321.30
9	4	T75301-28180 EMBLEM SUB-ASSY, <del>Coat</del>	1.00	101.60		101.60
			1.00	268.20		268.20

**LKK Auto Consultants** hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No legal modification(s) is allowed  
 • Supplementary ~~work~~ must be resurveyed receipt of vehicle is subject to final approval from insurer.  
 Acknowledged by Repairer  
 Signature:  
 Date:

For & on behalf of  
 Borneo Motors (Singapore) Pte Ltd  
 Customer's Signature

Charge Summary		Total
		5,838.60
		GST 8.00%
		467.09
Parts	1,908.60	
Labour	3,850.00	
Sublet	80.00	
Lubrication/Fluid	0.00	
Others	0.00	
	Less	0.00
	Amount Due	6,305.69