

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMN3689R

Make & Model: Mercedes Benz CLA180

Chassis number: WDD1173422N510733

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ X 1,532.00
2	Bootlid centre emblem	1	\$ X 78.00
3	Bootlid "CLA 180"	1	\$ X 83.00
4	Bootlid lock	1	\$ X 317.00
5	Bootlid lock catch	1	\$ X 56.00
6	Bootlid RH hinge	1	\$ X 189.00
7	Bootlid LH hinge	1	\$ X 189.00
8	Bootlid weatherstrip	1	\$ X 336.00
9	Rear bumper	1	\$ de 1,463.00
10	Rear bumper clips	1set	\$ 304 80.00
11	Rear bumper lower garnish	1	\$ out 313.00
12	Rear bumper lower garnish chrome	1	\$ out 139.00
13	Rear bumper towing cover	1	\$ X 36.00
14	Rear bumper RH corner reverse sensor	1	\$ X 257.00
15	Rear bumper RH side reverse sensor	1	\$ X 257.00
16	Rear bumper RH centre reverse sensor	1	\$ nu 257.00
17	Rear bumper LH centre reverse sensor	1	\$ nu 257.00
18	Rear bumper LH side reverse sensor	1	\$ X 257.00
19	Rear bumper LH corner reverse sensor	1	\$ X 257.00
20	Rear bumper reverse sensor rubber seal	1	\$ X 56.00
21	Rear bumper RH bracket	1	\$ X 56.00
22	Rear bumper LH bracket	1	\$ X 56.00
23	Rear bumper centre bracket	1	\$ 116.00
24	Rear bumper RH lower bracket	1	\$ X 42.00
25	Rear bumper LH lower bracket	1	\$ X 42.00
26	Rear bumper RH exhaust chrome cover	1	\$ X 289.00
27	Rear bumper LH exhaust chrome cover	1	\$ X 289.00
28	Rear bumper reinforcement	1	\$ bte 792.00
29	RH taillamp assy	1	\$ X 832.00
30	RH taillamp panel	1	\$ X 189.00
31	RH taillamp lock clips	1	\$ X 48.00
32	RH taillamp lower bracket	1	\$ X 48.00
33	RH headlamp frame sealing	1	\$ X 69.00
34	LH taillamp assy	1	\$ X 832.00
35	LH taillamp panel	1	\$ X 189.00
36	LH taillamp lock clips	1	\$ X 48.00
37	LH taillamp lower bracket	1	\$ X 48.00
38	LH headlamp frame sealing	1	\$ X 69.00
39	End panel	1	\$ bb 1,012.00
40	End panel inner garnish	1	\$ X 185.00
41	End panel inner garnish clips	1set	\$ X 80.00

42	Rear LH fender inner trim	1	\$ X	684.00
43	Rear LH fender inner trim clips	1set	\$ X	80.00
44	Rear RH fender inner trim	1	\$ X	684.00
45	Rear RH fender inner trim clips	1set	\$ X	80.00

\$ 13,268.00
 Parts less 10% \$ 1,326.80
 Total: \$ 11,941.20

No.	Special Nett Items	Qty	Amount S\$
1	Bootlid "C&C" emblem	1	\$ X 120.00
2	End panel joint sealant	1	\$ 40w 80.00

Total: \$ 200.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 500 1,500.00
2	Spray painting on affected areas and panels	\$ 500 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 60.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 80.00
5	Remove and refit bootlid reverse camera to assist repair	\$ X 100.00
6	Remove and replace bootlid inner mechanism to new bootlid	\$ X 150.00
7	Remove and replace rear bumper reverse sensors	\$ 30 100.00
8	Remove and replace rear inner trims and garnish to assist repair	\$ 60 280.00

Total: \$ 1,970.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Tanjini 97495774
 WP/ 23/1/23 @ 1115
 L/S Repair after repair
 Tanjini C/Chantawan
 - To check consistency of accident
 - To check part prices
 4 days

Spare Parts: \$ 11,941.20
 Special Nett: \$ 200.00
 Labour: \$ 1,970.00

Total Amount: \$ 14,111.20

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: