

REPAIR ESTIMATE

LKK-

DATE: 23.06.2023

SLP9361Y

INSURANCE: ALLIANZ (HS)MODEL: TOYOTA PRIUS G4AMVA: LIMITSVEHICLE NO.: SHA 903U - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Front Bumper	1		\$ 591.75	ph
	Front Bumper Centre Grille	1		\$ 301.90	?
	Front Bumper Lower Grille	1		\$ 193.18	de
	Front Bumper Hole Cover RH	1		\$ 28.38	mis
	Front Bumper Grille RH	1		\$ 85.10	ent
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	ner
	Front Bumper Side Brkt RH	1		\$ 82.30	chg
	FogLamp RH	1		\$ 920.00	?
	HeadLamp RH	1		\$ 2,735.28	air
	HeadLamp Support Panel RH	1		\$ 240.10	?
	Front Fender RH	1		\$ 1,111.93	bt
	Front Fender (Hybrid) RH	1		\$ 86.50	ner
	Front Fender Shield RH	1		\$ 198.50	ph
	Front Fender Shield Clips	10	\$ 2.20	\$ 22.00	ner
	Front Wheel Rim RH	1		\$ 1,570.55	dd
	Wiper Washer Tank With Motor	1		\$ 486.70	de
	SUB TOTAL			\$ 8,676.17	
	LESS 25%			\$ 2,169.04	
	DISCOUNTED TOTAL			\$ 6,507.13	
	Front Wheel Tyre RH	1		\$ 216.00	NETT
	Labour Charge				
	Panel Beating		525	\$ 800.00	
	Spray Painting Charge		500	\$ 600.00	
	Check Lightings		30	\$ 40.00	
	Tuff Kote		30	\$ 40.00	
	Wheel Alignment		80	\$ 120.00	
	Towing Fee - chit attached.		✓	\$ 60.00	
	TOTAL LABOUR			\$ 1,660.00	
	ESTIMATE TOTAL			\$ 8,383.13	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature:

Tanpin 97495719
 WP 7/3/23 @ 4 pm
 C/S Posing office

2-3 days


JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>27/6/23</u> Time Received: <u>1040</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)		4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>Fong Keng Fatt</u> Contact No. : <u>8700 6033</u> Vehicle No. : <u>SHA 903U</u> x Make / Model / Colour : <u>Chrysler PWR</u> x Email :		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery		6. Parts Replaced/Remarks: 	
7. Location: <u>New Bridge Rd</u>			8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi		
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____					

10. Odometer Reading : _____ ✓
Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player
☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
/ : Scratched O : Missing

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ OTHERS
Name of Driver : Cher
Vehicle No. : YM7317B
Time Dispatch : 1040
Time of Arrival : 1100
Time Completed : 1145

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

27/6/23
Date

1100
Time

Yagwa
Signature of Customer

4. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY

Date/Time: 23.06.2023 08:16

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5901333

JC NO305558562

JMER
3 CITYCAB PTE LTD
JMER NO. 7010070
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

REGN NO.: SHA 903U	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A22.	DATE/TIME IN 06.2023 10:05
YR OF MANU. 14.01.2020	TARGET DATE
CHASSIS CODE JTDKB3FU303090452	COMPLETION DATE/TIME:


JUNT CARD NO.

JOB DESCRIPTION

cident Date: 22.06.2023
TURE: 3P 22.06.2023

NO	LABOR CODE
0010	PB
0020	23-01

DESCRIPTION
PANEL BEATING-SHA 903U-TP
TOWING FEE



LED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHA 903U LIMITS

Vehicle No.: SHA 903U

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard