

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0593/2023/EQ
DATE : 23-Jun-23
WIP : 26105

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2023
YOUR INSURED VEH NO : GBC 1385 T

Allianz Insurance Singapore Pte Ltd

79 Robinson Road
#09-01
Singapore 068897
Attn: Motor Claims Dept

OWNER'S NAME : MS FARAHDIAN BTE ABDUL AZIZ
ADDRESS : 261 RIVER VALLEY ROAD
#15-20, ASPEN HEIGHTS
SINGAPORE 238307
TELEPHONE : HP +65 82345167
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7220104791
VEHICLE NO : **SMZ 1083 M**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 12/10/2020
ENGINE NO : DEM 025196
CHASSIS NO : WAUZZZF50LA022337
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Jun-23
PLACE OF ACCIDENT : JUNCTION OF CENTRAL BLVD AND SHEARES AVENUE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 1083 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	
2	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$ 300.00	
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASS.	S/N \$ 400.00	
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,600.00	
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,600.00	
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	
TOTAL LABOUR CHARGES		: \$ 4,660.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 1083 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REMOVE AND REINSTALL LHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	
8	TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$	6,500.00	
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 18,832.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 1083 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,763.00	
2	REAR BUMPER SECURING STRIP - UPPER	1	\$ 133.00	
3	REAR BUMPER SECURING STRIP - LOWER	1	\$ 264.00	
4	REAR BUMPER SPOILER	1	\$ 292.00	
5	REAR BUMPER BRACKET - LH	1	\$ 241.00	
6	REAR BUMPER REFLECTOR - LH INNER / OUTER	2	\$ 102.00	
7	REAR BUMPER GUIDE SECTION - LH	1	\$ 52.00	
8	REAR BUMPER GUIDE SECTION - LH UPPER	1	\$ 27.00	
9	REAR BUMPER HOLDING STRAP - LH	1	\$ 100.00	
10	REAR PARKING AID SENSOR - LH	1	\$ 272.00	
11	REAR PARKING AID SEAL RING	4	\$ 11.00	
12	REAR SIDE PANEL - LH	1	\$ 4,315.00	
13	REAR QUARTER WINDOW - LH	1	\$ 844.00	
14	WINDOW PRIMER	1	\$ 24.00	
15	ATTACHMENT PARTS	1	\$ 144.00	
16	ADHESIVE TAPES	1	\$ 230.00	
17	REAR WHEEL HOUSING LINER - LH	1	\$ 322.00	
18	REAR DOOR - LH	1	\$ 4,210.00	
19	REAR DOOR OUTER SEAL - LH	1	\$ 261.00	
20	BONDING AGENT	1	\$ 51.00	
SUB TOTAL SPARE PARTS			\$ 14,658.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 1083 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	CLEANING SOLUTION	1	\$ 80.00	
22	APPLICATOR	1	\$ 9.00	
23	REAR DOOR ATTACHMENT PARTS	1	\$ 191.00	
24	REAR DOOR CATCH - LH	1	\$ 141.00	
25	REAR ALUMINIUM RIM - LH	1	\$ 2,000.00	
26	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
27	REAR VENT TRIM	1	\$ 77.00	
28	ACRYLIC SEALANT	S/N	\$ 180.00	
29	CAVITY WAX	S/N	\$ 140.00	
30	STONE CHIP	S/N	\$ 180.00	
31	METAL FILLER POWDER	S/N	\$ 280.00	
32	1/4 GLASS SEALANT	S/N	\$ 100.00	
33	SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS		:	\$ 18,640.00	
TOTAL LABOUR CHARGES		:	\$ 18,832.00	
GRAND TOTAL		:	\$ 37,472.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT