

(08/11/13) WBS
ASS. REC. BY: Am

REF: CS/CTI 23006383/Rup3

925K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 8668R
at Workshop m/s ONE LINE MOTORWORKS
of 11, TUES BAY CLOSE #06-03
Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 65K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 59K

Veh No: PC 8668R Yr Regn: 2016 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MINI - VAN

Make: TOYOTA HIACE COM 4L3.0 A c.c 2992

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 349258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDY 22300274/6

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 2 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 04/06/23

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 26/06/23

Survey held at ONE LINE MOTORWORKS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR & O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) \$ + RS. \$1

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

One Line Motorworks Trading

11, Tuas Bay Close #06-03 West Star, Singapore 636996

Tel: 62622106

Company Reg No: 53375959E

Email: tricia.onelinemotorworks@gmail.com

6th June 2023

BY HAND

THIRD-PARTY CLAIM GBE9834B- REPAIR ESTIMATE FOR PC8668R

TRAFFIC ACCIDENT ON 24/05/2023, TRAFFIC ACCIDENT AT PIONEER ROAD NORTH (KIAN TECK DRIVE JUNCTION), NEAR SECURA S'PORE, SINGAPORE

To whomever it concerns,

We append below our repair estimate for PC8668R.

Repair Estimate

Parts required:

1. Front RHS Side Mirror <i>lro /</i>	\$	800.00
2. Rear RHS Member <i>bn / plus?</i>	\$	2500.00
3. Rear Side Glass (Black) <i>bn /</i>	\$	4000.00
4. Artwork Stencil <i>u /</i>	\$	800.00
5. Rim Cover <i>and /</i>	\$	200.00


Labour charges:

1. To supply panel beaters to replace rear RHS member	<i>280</i> \$1000 x 2 Days	\$	2000.00 <i>560</i>
2. To supply panel beaters to replace rear side glass	<i>150 X</i> \$350 x 2 Days <i>1.5</i>	\$	700.00 <i>225</i>
3. To supply electrician to replace front RHS side mirror	\$250 x 1 Day <i>100</i>	\$	250.00 <i>100</i>
4. To supply stencil artists to apply artwork stencil	<i>280</i> \$350 x 1 Day	\$	350.00 <i>250</i>
5. To spray paint affected panels	<i>280 X 2.5</i> \$800 /panel	\$	3200.00 <i>625</i>

Total repair costs:

\$ 14,800.00

This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.



Neo Say Pheng
(HP: 9797 1868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pheng
At 90010068
4 days
4/5
26/06/23 @ 1150
Reg after Repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	925H
Vehicle No.:	PC8668R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2598599
Chassis No.:	KDH2230027416
Maximum Power Output:	-
Open Market Value:	\$40,955.00
Original Registration Date:	09 Jun 2016
First Registration Date:	09 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$2,048.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	08 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$18,348.00
COE Rebate Amount:	\$5,437.00
Total Rebate Amount:	\$5,437.00

The information contained herein is correct as at 29 Jun 2023

OK

Toyota Hiace Commuter 3.0A GL

\$65,000 Instalment \$1,837/mth

DIRECT OWNER

Shortlist

Paperwork Support

Loan Calculator

sgccarmart

SAVE UP TO **\$600**
ON YOUR CAR INSURANCE RENEWAL!

> Get Quotes Now

Overview Financial Photo Research

Depreciation	<i>i</i> \$22,070 / year
Reg. Date	09-Jun-2016 (2yrs 11mths 10days COE left)
Lifespan	<i>i</i> 08-Jun-2036
Manufactured	<i>i</i> 2016
Mileage	-
Transmission	Auto
Engine Cap	2,982 cc
Curb Weight	<i>i</i> 2,140 kg
Fuel Type	Diesel
COE	<i>i</i> \$30,846
OMV	<i>i</i> \$42,169
ARF	<i>i</i> \$2,109
Dereg Value	<i>i</i> \$9,085 as of today
No. of Owners	<i>i</i> 4
Type of Veh	Bus/Mini Bus