



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/III23003039/Dvy3-1	
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/III23003039/43	Date: 23/03/2023 23/06/2023
		Code: III2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLK 3765G	Veh. Inspected	SJR 2629K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JACELYN LOH	Assign Date	23/03/2023 23/06/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/03/2023	Inspection Date	27/03/2023
Survey held at	CHIP SOON AUTO SUPPLY CO. BLK 9002 #01-74 TAMPINES STREET 93 TAMPINES INDUSTRIAL PARK A SINGAPORE 528836		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			