

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KLV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

GBJ2249K

DATE: 23.06.2023

INSURANCE: INCOME (L/S)

MODEL: Hyundai Ioniq

SURVEYOR: LKK-

VEHICLE NO.: SHA7062A

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH / RH	2	\$ 138.10	\$ 276.20
	Rear Bumper Side Brackets LH / RH	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH / RH	2	\$ 41.45	\$ 82.90
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper FogLamp	1		\$ 201.50
	Rear Smart Key Antenna	1		\$ 40.50
	BootLid Emblem - Hybrid	1		\$ 24.30
	BootLid Emblem - Ioniq	1		\$ 31.30
	BootLid Assy	1		\$ 2,549.70
	BootLid Lower Glass - Black	1		\$ 584.90
	BootLid Spoiler	1		\$ 665.40
	BootLid Third Brake Lamp	1		\$ 385.60
	BootLid Lamp RH / LH	2	\$ 822.00	\$ 1,644.00
	TailLamp RH / LH	2	\$ 935.40	\$ 1,870.80
	SUB TOTAL			\$ 10,049.95
	LESS 20%			\$ 2,009.99
	DISCOUNTED TOTAL			\$ 8,039.96
	BootLid ComfortDelGro	1		\$ 30.00
	BootLid 65521111	1		\$ 30.00
	BootLid ZIG	1		\$ 40.00
	Reverse Sensors	1		\$ 180.00
	Rear No.Plate With Trim Cover	1		\$ 55.00
	Rear Windscreen Sealant	2	\$ 46.00	\$ 92.00
	S/NETT SUB			\$ 427.00
	LESS 10%			\$ 42.70
	S/NETT TOTAL			\$ 384.30
	Rear Fender Adv.Sticker RH / LH	2	\$ 100.00	\$ 200.00
	BootLid Adv.Sticker	1		\$ 100.00
	Rear Bumper Mat			\$ 50.00
	SPARE PARTS TOTAL			\$ 8,774.26
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 600.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Rear Windscreen Glasses			\$ 250.00
	TOTAL LABOUR			\$ 1,770.00
	ESTIMATE TOTAL			\$ 10,544.26


This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

tanj... 4745714
 up... 23/6/23 C 4 pm
 L/S Resurvey after repair
 tanj... C 1 hour... 3 days

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyal Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time: 23.06.2023 13:35 Page : 1

Job: ARC Repair TP(CLSO)1		JOB CARD Sales Order: 5901421		JC NO305558569	
Customer: COMFORT TRANSPORTATION PTE LTD		REGN NO.: SHA7062A		MILEAGE	
MER NO: 7010045		MAKE: HYUNDAI		FUEL	
ISS 383 SIN MING DRIVE		MODEL: IONIQ(G2)		E.....1/2.....F	
Singapore SINGAPORE 575717		23.06.2023 11:00		DATE/TIME IN	
(R) 65508755		YR OF MANU. 02.04.2019		TARGET DATE	
(P)		CHASSIS CODE: KMHC851CVKU141563		COMPLETION DATE/TIME:	
UNIT CARD NO.					

cident Date: 22.06.2023		JOB DESCRIPTION	
TURE: 3P 22.06.2023			
NO	LABOR CODE	DESCRIPTION	
0010	PB	LUMPSUM REPAIR-SHA7062A-TP	
			

ED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
dgement Slip		Exit Pass	
o.: SHA7062A		Vehicle No.: SHA7062A	
LIMITS			
Service Advisor		Signature/Date	
Name of Service Advisor		Date	
urned to Service Reception upon collection		To be kept by Security Guard	