

ASS. REC. BY: Tauji

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seent _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
SumanVeh No: SAC / 3736Yr Regn: 2020, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundaicc 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading 40315

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4C851CVL4190451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Washube

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 23/6/23Survey held at Washube

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.A. / F

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1373G
MAKE HYUNDAI
MODEL IONIQ

DATE: 23.06.23
MVA JUMANI
DOA: 23.06.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			Key \$459.40
10	REAR BUMPER CLIPS			key \$22.00
1	REAR BUMPER CENTRE MOULDING			key \$451.25
1	REAR BUMPER BEAM			? \$394.80
1	REAR FOG LAMP			X \$201.50
1	ANTENNA SMARTKEY			? \$40.50
	SUB TOTAL			\$1,569.45
	LESS 25%			\$313.89
	DISCOUNTED TOTAL			\$1,255.56
	REAR NUMBER PLATE			key \$55.00 NET
	REVERSE SENSOR			? \$180.00 NET
	REAR BUMPER MAT			X \$50.00 NET
	SUB TOTAL			\$285.00
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINT			250 \$300.00
	REMOVE/REFIX REVERSE SENOR			30 \$50.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$750.00
				\$2,290.86
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tamplin 97495744
WP 73/2/23 4pm
02 days
Tamplin e (handwritten)
L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 23.06.2023 14:44

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5901464


JC NO305558662

OMER NO. 7010045	REGN NO.: SHC1373G	MILEAGE
ESS 383 SIN MING DRIVE	MAKE: HYUNDAI	FUEL E.....1/2.....F
Singapore SINGAPORE 575717	MODEL IONIQ(G3)	DATE/TIME IN 23.06.2023 11:30
(R) 65508755 (O)	YR OF MANU. 18.03.2020	TARGET DATE
(P)	CHASSIS CODE KMHC851CVLU190451	COMPLETION DATE/TIME:
JUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 23.06.2023
ATURE: 3P.23.06.23

NO LABOR CODE DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHC1373G

JU INCOME

Vehicle No.:

SHC1373G

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard